# Reserve Management Plan Type 2 Engagement Reserve Study Update with On-Site Analysis

For 30-Year Projection Period Beginning January 1, 2025



# January 1, 2025

# **Table of Contents**

Cover - Reserve Management Plan	1
Table of Contents	
Preparers Report on Reserve Study	3
Statement of Position	5
Summary of Major Components	6
Cash Flow - Annual	7
Cash Flow - Chart	8
Expenditures - Matrix Category	9
Expenditures - Matrix Items	12
Component List - Summary	18
Component List - Category - Chart	19
Disclosures	20
Supplementary Information	23
Component List - Detail	24
Cover - Supplemental Schedules	31
Preparers Report on Supplemental Information	32
Percent Funded - Annual - Ending Balance	33
Percent Funded - Annual - Chart	34
Expenditure - By Year	35
Preparers Report on Reserve Study Statement of Position Summary of Major Components Cash Flow - Annual Cash Flow - Chart Expenditures - Matrix Category Expenditures - Matrix Items Component List - Summary Component List - Category - Chart Disclosures Supplementary Information Component List - Detail Cover - Supplemental Schedules Preparers Report on Supplemental Information Percent Funded - Annual - Ending Balance Percent Funded - Annual - Chart Expenditure - By Year Expenditure - By Component	
Preparers Report on Reserve Study Statement of Position Summary of Major Components Cash Flow - Annual Cash Flow - Chart Expenditures - Matrix Category Expenditures - Matrix Items Component List - Summary Component List - Category - Chart Disclosures Supplementary Information Component List - Detail Cover - Supplemental Schedules Preparers Report on Supplemental Information Percent Funded - Annual - Ending Balance Percent Funded - Annual - Chart	



Preparer's Report on Reserve Study

Type 2 Reserve Management Plan Reserve Study Update with On-Site Analysis

For 30-Year Projection Period Beginning January 1, 2025

Board of Directors Springwood Villas 2 Pinellas Park, FL

Description of Reserve Management Plan Engagement and Reserve Study Report

A reserve management plan engagement involves the reserve professional providing assistance to management of Springwood Villas 2 by helping them identify key factors, develop assumptions, gather and assemble information, and develop a financial model so they may consider the results based upon their stated assumptions.

A Type 2 reserve study engagement is based on an updated on-site analysis. The on-site analysis of Springwood Villas 2 upon which this reserve management plan is based was performed by Gary Porter, RS, FMP, RRC, CPA of Facilities Advisors on February 6, 2025.

The attached basic financial exhibits and disclosures comprise a Type 2 Reserve Study report of Springwood Villas 2. The basic financial exhibits comprising this reserve study report are the statement of position and summary component list as of January 1, 2025, statements of projected cash flows and expenditures for the 30-year period beginning January 1, 2025, and related disclosures that provide important information regarding the basic financial exhibits.

Management's Responsibility for Reserve Study

The Governing Body of Springwood Villas 2 is responsible for the preparation and fair presentation of this reserve study report in accordance with Generally Accepted Reserve Study Principles.

Reserve Professional's Responsibility

Our responsibility is to perform our reserve management plan engagement and compile the reserve study report in accordance with Generally Accepted Reserve Study Standards.

Report on Reserve Study

Our reserve management plan engagement was performed in accordance with Generally Accepted Reserve Study Standards. A reserve study involves performing procedures to identify, quantify and evaluate condition of components based upon a visual observation for the purpose of making a financial projection. The procedures selected are based on the reserve professional's judgment. We believe that the procedures we have performed are sufficient and appropriate to support the reserve study report as presented. We are not responsible for any events subsequent to the date of this report.

We have compiled the accompanying reserve study report of Springwood Villas 2, comprised of the financial exhibits referred to above in accordance with Generally Accepted Reserve Study Principles.

This reserve study report was prepared using software meeting the reserve study calculation and software standards of the International Capital Budgeting Institute.



We are not aware of any material modifications that should be made to the financial exhibits referred to above, based upon the stated significant assumptions and exclusions, for them to be presented in conformity with Generally Accepted Reserve Study Principles.

This reserve study report is restricted to the management and members of the Springwood Villas 2 and should not be relied upon by others not involved in the establishment of the significant assumptions and exclusions upon which this report is based. Readers of the reserve study report should consider the significant assumptions, excluded components, and general exclusions in forming their own conclusions regarding the reserve study report.

#### Required Supplementary Information

Generally Accepted Reserve Study Standards require that the component list compiled at the major or minor component level be presented to supplement the basic financial exhibits. This component list is the responsibility of the Springwood Villas 2's management and was used to prepare the basic financial exhibits. The information contained in this list has been subjected to the procedures applied in the compilation of the reserve study report, and we are not aware of any material modifications that should be made thereto.

#### Regulatory Information

In the case of common interest realty associations located in the U.S.A., Generally Accepted Reserve Study Standards require that regulatory disclosures be presented to supplement the basic financial exhibits. Regulatory Disclosures consist of supplemental information required by the Financial Accounting Standards Board and any disclosures required by state or local jurisdictions. Such information is the responsibility of the Springwood Villas 2's management and was derived from the component list used to prepare the reserve study report. The information has been subjected to the procedures applied in the compilation of the basic reserve study report, and we are not aware of any material modifications that should be made thereto.

Facilities Advisors Florida Greg Libke, RS June 28, 2025



#### Statement of Position

Projection period: January 1, 2025 to 2054
Type of Project: Planned Development

Number of Units: 219

Location: Pinellas Park, FL
Project Construction date: January 1, 1972
On-Site analysis performed by: Greg Libke, RS, RSS
Component analysis performed by: Greg Libke, RS, RSS
Report prepared by: Greg Libke, RS, RSS

No special assessments are considered necessary during the 30-year projection period.

Current Replacement Cost of All Components	\$ 1,066,717
Future Replacement Cost of All Components	\$ 1,366,821
Projected Balance of Reserve Funds at January 1, 2025	\$ 719,661
100% Funded Amount at January 1, 2025	\$ 653,735
Percent Funded at January 1, 2025	\$110.08 %
Reserve (Surplus)/Deficit – Average per Unit at January 1, 2025	\$ -301
Projected Reserve Contribution	\$ 52,584
Average Annual Reserve Contribution Per Unit	\$ 240
Monthly Reserve Contribution First Year of Projection	\$ 4,382
Average Monthly Reserve Contribution Per Unit	\$ 20
Projected Special Assessment	\$ 0
Projected Inflation Rate	3.00 %
Projected Interest Rate	2.00 %

#### Components Excluded from This Report

Major Component	Reason Excluded						
Building Structures	Lifetime Component						
Utilities - Underground and in Structure	Long-lived Component – Never previously included in						
	study, and Excluded per Board decision						
Street Base	Lifetime Component						
Hardscape – sidewalks and curbs	Lifetime Component						
Irrigation Lines and Sprinklers	Included in Operating Budget						
Major Tree Trimming	Included in Operating Budget						
Landscape / Plant Replacement	Included in Operating Budget						

Summary of major components is presented on next page



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Summary of Major Components

	Estimated		Estimated
	Remaining		Future
	Useful Lives		Replacement
Categories	Years		Cost
Equipment	1- 4	<del>-</del> \$	31,855
Fitness	1		7,725
Flooring	18-29		86,129
Furniture	0-23		52,667
HVAC	1-14		49,239
Irrigation	10		6,720
Lakes	5-15		13,586
Lighting	5		5,796
Painting	1		24,720
Pavement	1- 9		314,933
Pool	0-15		108,475
Remodel	1-13		103,976
Roof	6-20		154,101
Safety/Security	0- 4		45,251
Sewer	1- 5		166,093
Walls, Gates, Fence	0-24		189,762
Windows, Doors	5		5,796
		\$	1,366,824



# Springwood Villas 2 Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Cash Flow - Annual

Period	Beginning Balance	Contribution	Interest Earned	Expenditures	Ending Balance
01/25 - 12/25	\$ 719,661.19	\$ 52,584.72	\$ 12,666.88	\$ 123,500.00	\$ 661,412.79
01/26 - 12/26	661,412.79	81,506.28	9,126.06	260,865.53	491,179.60
01/27 - 12/27	491,179.60	85,581.60	9,714.48	54,848.54	531,627.14
01/28 - 12/28	531,627.14	89,860.68	10,924.31	36,726.55	595,685.58
01/29 - 12/29	595,685.58	94,353.72	12,238.13	37,985.93	664,291.50
01/30 - 12/30	664,291.50	99,071.40	12,003.61	124,187.25	651,179.26
01/31 - 12/31	651,179.26	104,025.00	5,098.81	470,178.97	290,124.10
01/32 - 12/32	290,124.10	109,226.28	6,467.15	25,212.42	380,605.11
01/33 - 12/33	380,605.11	114,687.60	8,474.97	18,665.86	485,101.82
01/34 - 12/34	485,101.82	120,421.92	10,138.69	44,688.49	570,973.94
	719,661.19	951,319.20	96,853.09	1,196,859.54	570,973.94

Period	Beginning Balance	Contribution	Interest Earned	Expenditures	Ending Balance
01/35 - 12/35	\$ 570,973.94	\$ 126,443.04	\$ 11,766.93	\$ 53,252.68	\$ 655,931.23
01/36 - 12/36	655,931.23	132,765.24	8,706.31	303,517.50	493,885.28
01/37 - 12/37	493,885.28	139,403.52	10,855.47	26,661.73	617,482.54
01/38 - 12/38	617,482.54	146,373.60	11,614.95	120,030.60	655,440.49
01/39 - 12/39	655,440.49	153,692.28	13,262.08	78,276.52	744,118.33
01/40 - 12/40	744,118.33	161,376.96	11,758.91	252,585.46	664,668.74
01/41 - 12/41	664,668.74	169,445.76	8,596.17	337,417.62	505,293.05
01/42 - 12/42	505,293.05	177,918.12	9,451.16	131,236.08	561,426.25
01/43 - 12/43	561,426.25	186,813.96	11,969.00	64,241.32	695,967.89
01/44 - 12/44	695,967.89	196,154.64	15,215.48	41,645.77	865,692.24
	570,973.94	1,590,387.12	113,196.46	1,408,865.28	865,692.24


Period	Beginning Balance	Contribution	Interest Earned	Expenditures	Ending Balance
01/45 - 12/45	\$ 865,692.24	\$ 205,962.36	\$ 15,489.82	\$ 209,734.67	\$ 877,409.75
01/46 - 12/46	877,409.75	216,260.52	11,242.85	446,968.32	657,944.80
01/47 - 12/47	657,944.80	227,073.60	14,871.46	35,831.13	864,058.73
01/48 - 12/48	864,058.73	238,427.28	18,913.95	47,829.87	1,073,570.09
01/49 - 12/49	1,073,570.09	250,348.56	20,271.14	202,547.60	1,141,642.19
01/50 - 12/50	1,141,642.19	262,866.00	22,382.88	170,904.61	1,255,986.46
01/51 - 12/51	1,255,986.46	276,009.36	11,582.79	855,665.34	687,913.27
01/52 - 12/52	687,913.27	289,809.84	16,284.83	26,655.47	967,352.47
01/53 - 12/53	967,352.47	304,300.32	20,916.94	86,334.97	1,206,234.76
01/54 - 12/54	1,206,234.76	319,515.24	23,763.12	196,419.75	1,353,093.37
	865,692.24	2,590,573.08	175,719.78	2,278,891.73	1,353,093.37



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Cash Flow - Chart





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Expenditures - Matrix Category

Category	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034
Equipment		20,600			11,255			<u> </u>		
Fitness		7,725				8,695				9,786
Furniture	2,500	2,575			8,160	9,274	2,985			9,460
HVAC		6,695	25,992							
Lakes						5,796				
Lighting						5,796				
Painting		24,720								
Pavement		38,901	5,305	23,750	2,814	13,911	281,519	14,758	12,332	25,443
Pool	51,500		3,713		13,506	32,460	4,179	10,454		
Remodel		5,150	19,839			13,911			6,334	
Roof							2,388			
Safety/Security	43,000				2,251					
Sewer		154,500				11,593	179,108			
Walls, Gates, Fence	26,500			12,976		16,954				
Windows, Doors						5,796				
_	123,500	260,866	54,849	36,727	37,986	124,187	470,179	25,212	18,666	44,688

Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Expenditures - Matrix Category

Category	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044
Equipment	·	·			15,126		32,094			
Fitness				11,014				12,396		
Flooring									34,049	
Furniture	6,720	3,461		18,357	10,966	12,464	4,012			16,220
HVAC	6,720				9,832		10,431	40,495		
Irrigation	6,720									
Lakes						7,790				
Lighting						7,790				
Painting		33,222								
Pavement		52,279		31,919	11,344	18,696	41,349	19,834	16,573	25,426
Pool					31,008	74,003	5,616	47,933		
Remodel		6,921	26,662	58,741		18,696			8,512	
Roof									3,405	
Safety/Security						66,993	3,209			
Sewer	13,439	207,635				15,580	240,706			
Walls, Gates, Fence	19,655					22,785		10,578	1,702	
Windows, Doors						7,790				
	53,253	303,518	26,662	120,031	78,277	252,585	337,418	131,236	64,241	41,646



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Expenditures - Matrix Category

Category	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054
Equipment					20,328			<u> </u>		
Fitness		13,952				15,703				17,674
Flooring										52,080
Furniture	4,515	4,651		4,934	14,738	16,750	5,391		28,599	17,085
HVAC						10,469				15,318
Lakes	9,031									
Lighting						10,469				
Painting		44,647								
Pavement		79,560		42,896	5,082	25,125	519,237	26,655	22,273	34,170
Pool		15,813			24,394	5,234	7,548		19,447	60,092
Remodel		9,301	35,831			25,125			11,440	
Roof	151,713									
Safety/Security									4,576	
Sewer	18,061	279,044				20,938	323,489			
Walls, Gates, Fence	26,414				138,006	30,622				
Windows, Doors						10,469				
-	209,735	446,968	35,831	47,830	202,548	170,905	855,665	26,655	86,335	196,420



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Expenditures - Matrix Items

Component	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034
Asphalt - Overlay							250,751			
Asphalt - Repair & Reseal		15,450			2,814		17,911			3,262
Audio/Visual Equipment - Replace		20,600								
Billiard Table - Refurbish					3,377					3,914
Bldg Exterior - Repaint		24,720								
Bldg Exterior Gutters - Replace							2,388			
Bldg Exterior Roof - Replace										
Concrete - Partial Replace		12,360		13,113		13,911		14,758		15,657
Defibrillators - Replace					2,251					
Doors - Partial Replace						2,898				
Entry FOB System - Replace	22,000									
Exhaust Fan - Replace										
Fence Metal - Replace										
Fence Vinyl - Replace										
Fitness Equipment - Replace		7,725				8,695				9,786
Flooring LVT - Replace										
Flooring Tile - Replace										
Fountain - Refurbish					11,255					
Furniture Chairs - Replace										
Furniture Poker Table - Replace										
Furniture Tables - Replace										
Gate Metal - Replace										
Gazebo - Refurbish					4,783					5,545
HVAC 3-Ton - Replace										
HVAC 4-Ton - Replace		6,695	6,896							
HVAC 5-Ton - Replace			19,096							
Irrigation System - Repairs										
Lake - Dredge & Shoreline Remediat	0									
Lake Controller - Replace						5,796				

PRN:06/28/2025

See Preparer's Report

See Disclosures and Summary of Significant Assumptions

Page 12 of 104



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Expenditures - Matrix Items

Component	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034
Lighting - Replace						5,796				
Paver - Repair & Reseal		11,091		10,638			12,857		12,332	
Pool - Resurface	43,000									
Pool Chlorination - Replace							4,179			
Pool Filter - Replace			3,713							
Pool Furniture - Replace					13,506					
Pool Heater - Replace	8,500					29,561		10,454		
Pool Sauna - Refurbish						2,898				
Remodel Auditorium - Remodel						11,593			6,334	
Remodel Billiard Rm - Remodel						2,319				
Remodel Clubhouse Restrooms - Rem										
Remodel Kitchen - Remodel		5,150								
Remodel Meeting Rm - Remodel			19,839							
Security System - Replace	21,000									
Sewer Line - Repairs		154,500					179,108			
Shuffleboard - Resurface			5,305							6,524
Shuffleboard Benches Wood - Repair		2,575					2,985			
Shuffleboard Shade Structures - Refur	11,875			12,976						
Signage Monument - Refurbish										
Signage Streets/Misc - Repair & Replac						9,274				
Storm Water Drainage - Repairs						11,593				
Wall Block - Repair	14,625					16,954				
Windows - Partial Replace						2,898				
Windscreen - Replace	2,500									
	123,500	260,866	54,849	36,727	37,986	124,187	470,179	25,212	18,666	44,688

PRN:06/28/2025

See Preparer's Report
See Disclosures and Summary of Significant Assumptions
Page 13 of 104



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Expenditures - Matrix Items

Component	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044
Asphalt - Overlay		·	·			·	<u> </u>	·		
Asphalt - Repair & Reseal		20,764			3,781		24,071			4,384
Audio/Visual Equipment - Replace							32,094			
Billiard Table - Refurbish					4,538					5,261
Bldg Exterior - Repaint		33,222								
Bldg Exterior Gutters - Replace									3,405	
Bldg Exterior Roof - Replace										
Concrete - Partial Replace		16,611		17,622		18,696		19,834		21,042
Defibrillators - Replace							3,209			
Doors - Partial Replace						3,895				
Entry FOB System - Replace						34,275				
Exhaust Fan - Replace						3,116				
Fence Metal - Replace								10,578		
Fence Vinyl - Replace										
Fitness Equipment - Replace				11,014				12,396		
Flooring LVT - Replace										
Flooring Tile - Replace									34,049	
Fountain - Refurbish					15,126					
Furniture Chairs - Replace										3,507
Furniture Poker Table - Replace	3,360									
Furniture Tables - Replace										
Gate Metal - Replace									1,702	
Gazebo - Refurbish					6,429					7,452
HVAC 3-Ton - Replace	6,720									
HVAC 4-Ton - Replace					9,832		10,431	10,744		
HVAC 5-Ton - Replace								29,751		
Irrigation System - Repairs	6,720									
Lake - Dredge & Shoreline Remedi	atio					7,790				
Lake Controller - Replace										

PRN:06/28/2025

See Preparer's Report

See Disclosures and Summary of Significant Assumptions

Page 14 of 104



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Expenditures - Matrix Items

Component	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044
Lighting - Replace			•			7,790		,		
Paver - Repair & Reseal		14,905		14,296			17,279		16,573	
Pool - Resurface						66,993				
Pool Chlorination - Replace							5,616			
Pool Filter - Replace								5,785		
Pool Furniture - Replace					18,151					
Pool Heater - Replace					12,857			42,148		
Pool Sauna - Refurbish						3,895				
Remodel Auditorium - Remodel						15,580			8,512	
Remodel Billiard Rm - Remodel						3,116				
Remodel Clubhouse Restrooms - Rem				58,741						
Remodel Kitchen - Remodel		6,921								
Remodel Meeting Rm - Remodel			26,662							
Security System - Replace						32,717				
Sewer Line - Repairs		207,635					240,706			
Shuffleboard - Resurface					7,563					
Shuffleboard Benches Wood - Repair		3,461					4,012			
Shuffleboard Shade Structures - Refur										
Signage Monument - Refurbish				18,357						
Signage Streets/Misc - Repair & Replac						12,464				
Storm Water Drainage - Repairs	13,439					15,580				
Wall Block - Repair	19,655					22,785				
Windows - Partial Replace						3,895				
Windscreen - Replace	3,360									
_	53,253	303,518	26,662	120,031	78,277	252,585	337,418	131,236	64,241	41,646

PRN:06/28/2025

See Preparer's Report
See Disclosures and Summary of Significant Assumptions
Page 15 of 104



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Expenditures - Matrix Items

Component	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054
Asphalt - Overlay				,	·	•	452,884			
Asphalt - Repair & Reseal		27,904			5,082		32,349			5,891
Audio/Visual Equipment - Replace										
Billiard Table - Refurbish					6,098					7,070
Bldg Exterior - Repaint		44,647								
Bldg Exterior Gutters - Replace										
Bldg Exterior Roof - Replace	151,713									
Concrete - Partial Replace		22,324		23,683		25,125		26,655		28,279
Defibrillators - Replace									4,576	
Doors - Partial Replace						5,234				
Entry FOB System - Replace										
Exhaust Fan - Replace										
Fence Metal - Replace										
Fence Vinyl - Replace					138,006					
Fitness Equipment - Replace		13,952				15,703				17,674
Flooring LVT - Replace										52,080
Flooring Tile - Replace										
Fountain - Refurbish					20,328					
Furniture Chairs - Replace										
Furniture Poker Table - Replace										
Furniture Tables - Replace				4,934						
Gate Metal - Replace										
Gazebo - Refurbish					8,639					10,015
HVAC 3-Ton - Replace						10,469				
HVAC 4-Ton - Replace										15,318
HVAC 5-Ton - Replace										
Irrigation System - Repairs										
Lake - Dredge & Shoreline Remediat	io									
Lake Controller - Replace	9,031									

PRN:06/28/2025

See Preparer's Report

See Disclosures and Summary of Significant Assumptions

Page 16 of 104



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Expenditures - Matrix Items

Component	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054
Lighting - Replace						10,469				
Paver - Repair & Reseal		20,031		19,213			23,221		22,273	
Pool - Resurface										
Pool Chlorination - Replace							7,548			
Pool Filter - Replace										
Pool Furniture - Replace					24,394					
Pool Heater - Replace		15,813							19,447	60,092
Pool Sauna - Refurbish						5,234				
Remodel Auditorium - Remodel						20,938			11,440	
Remodel Billiard Rm - Remodel						4,188				
Remodel Clubhouse Restrooms - Rem										
Remodel Kitchen - Remodel		9,301								
Remodel Meeting Rm - Remodel			35,831							
Security System - Replace										
Sewer Line - Repairs		279,044					323,489			
Shuffleboard - Resurface		9,301					10,783			
Shuffleboard Benches Wood - Repair		4,651					5,391			
Shuffleboard Shade Structures - Refur										
Signage Monument - Refurbish									28,599	
Signage Streets/Misc - Repair & Replac						16,750				
Storm Water Drainage - Repairs	18,061					20,938				
Wall Block - Repair	26,414					30,622				
Windows - Partial Replace						5,234				
Windscreen - Replace	4,515									
	209,735	446,968	35,831	47,830	202,548	170,905	855,665	26,655	86,335	196,420

See Preparer's Report

See Disclosures and Summary of Significant Assumptions

Page 17 of 104

PRN:06/28/2025



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future


# Component List - Summary

Category	Service Date	Replace Life	Current Cost	Future Cost
Fauinment	01/11 01/10	1.00 4.00	¢ 20 000 00	¢ 21 0EE 00
Equipment	01/11-01/19	1:00 - 4:00	\$ 30,000.00	\$ 31,855.09
Fitness	01/22-01/22	1:00 - 1:00	7,500.00	7,725.00
Flooring	01/13-01/24	18:00 -29:00	42,100.00	86,128.76
Furniture	01/15-01/24	0:00 -23:00	39,750.00	52,666.57
HVAC	01/11-01/24	1:00 -14:00	42,500.00	49,238.46
Irrigation	01/15-01/15	10:00 -10:00	5,000.00	6,719.58
Lakes	01/90-01/15	5:00 -15:00	10,000.00	13,586.21
Lighting	01/20-01/20	5:00 - 5:00	5,000.00	5,796.37
Painting	01/16-01/16	1:00 - 1:00	24,000.00	24,720.00
Pavement	01/11-01/24	1:00 - 9:00	270,002.50	314,931.35
Pool	01/05-01/21	0:00 -15:00	100,500.00	108,474.06
Remodel	01/13-01/23	1:00 -13:00	80,700.00	103,975.32
Roof	01/19-01/20	6:00 -20:00	86,000.00	154,101.44
Safety/Security	01/10-01/17	0:00 - 4:00	45,000.00	45,251.02
Sewer	01/21-01/25	1:00 - 5:00	160,000.00	166,092.74
Walls, Gates, Fence	01/90-01/24	0:00 -24:00	113,665.00	189,763.17
Windows, Doors	01/20-01/20	5:00 - 5:00	5,000.00	5,796.38
		-	1,066,717.50	1,366,821.52



Analysis Date - January 1, 2025
Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Category - Chart





#### **Disclosures**

#### Site Analysis

Springwood Villas 2 is a planned development association located in Pinellas Park, FL. The Association consists of 219 units located at the corner of U.S 19 Frontage Rd & Springwood Blvd, encompassing approximately 31 acres. The units were constructed as a single phase in January 1, 1972. The project consists of a Clubhouse with Pool, Rec Courts, Concrete streets, Common tracts, and Lakes.

The site analysis was performed on February 6, 2025 by Greg Libke of Facilities Advisors Florida. The Association manager was interviewed during the site analysis regarding component existence, maintenance activities, dates last repaired/replaced, and actual or bid costs, if known. Site analysis procedures included:

Review of Google Earth satellite images

Tour of Association common areas

Identification and quantification / measurement of common area components

Component condition assessment

The site analysis was performed as a limited scope visual observation. No destructive or invasive testing was performed. The condition of components may be assessed differently if destructive / invasive testing was performed, but such testing is beyond the scope of a reserve study.

#### Component Analysis

Components considered for inclusion in the reserve study report are all those components that are the maintenance responsibility of the Association that are anticipated to require future major repair or replacement under the assumption that such components are subject to normal maintenance activities and normal wear and tear. Components with a useful life of less than two years or a cost of \$1,000 have generally been excluded from this analysis, as such items are considered to be part of the Association's operating budget.

The component list was compiled based upon the previous reserve study, the tour of association common areas, inquiry of Association management and maintenance staff, and selected vendors providing maintenance services to the Association. The component list is believed to be complete, except for the exclusions noted below, which are considered normal exclusions.

Estimated future major repair and replacement costs are generally based on current replacement costs projected to estimated repair or replacement date, applying an inflation factor of 3.00% for the entire 30-year financial projection period.

Current estimated replacement costs are derived from a variety of sources including; actual prior costs, current bids, vendor or contractor estimates, management's estimates, Facilities Advisors International's cost database, or cost estimator manuals. This data is considered reliable and has been relied upon in the determination of current cost. Current cost includes material or product cost, labor, overhead, delivery, and sales tax.



#### General Exclusions from the analysis are:

Excluded Conditions	Reason for Exclusion
Building code or zoning violations or upgrades	Outside scope of study
Structural stability or engineering analysis	Outside scope of study
Environmental conditions *	Outside scope of study
Geological stability or soil conditions	Outside scope of study
Soil contamination	Outside scope of study
Hydrological conditions	Outside scope of study
Mold or fungus	Outside scope of study
Termites or other pest control	Outside scope of study
Risks of wildfire, flood or seismic activity	Outside scope of study
Water quality or testing	Outside scope of study
Illegal or controlled substances	Outside scope of study
Building values or appraisals	Outside scope of study
Adequacy of efficiency of any system or	Outside scope of study
component	
Information not provided by the association necessary to identify all components	Outside scope of study

<sup>\*</sup> Asbestos, radon, formaldehyde, lead, water or air quality, electromagnetic radiation or other environmental hazards.

#### Financial Analysis

The financial projection was prepared using the pooled cash flow method. Under this method, aggregate expenditures are projected to future estimated repair or replacement dates considering inflation at 3.00%. Actual expenditures may vary from estimated expenditures, and the differences may be significant.

Reserve fund revenues consist of member assessments and interest earned (and other income). Interest income has been estimated at 2.00%. The funding plan does not contain an income tax expense related to interest earned, as income taxes are paid from the operating fund. The projected annual assessment has been subjected to an annual increase factor for the projection period. This annual assessment adjustment factor is necessary to counteract the effects of inflation on projected expenditures.

Replacement reserves are funded at a level of 110.08% as of January 1, 2025 using the inflation adjusted method of calculating percent funded.

The beginning balance of reserve funds was estimated at \$ 719,661, based on information provided by management. The beginning balance of reserve funds was provided by Association management.

Total Funds available for reserves beginning balance

<u>\$ 719,661</u>



#### Significant Assumptions

The following significant assumptions were used in the preparation of this reserve study report. If the actual replacement costs or remaining lives vary from the assumptions used in this analysis, the impact could be significant on future assessments. Accordingly, an annual review of the analysis is necessary to see if the Board, within its authority, should increase the regular assessments, pass special assessments or reschedule future replacement dates.

- Generally, only long-term major repair and replacement activities for components with a life of 2 years or longer and a cost of \$1,000 or more have been considered in this analysis. A group of items with individual cost of less than \$1,000 are included if the aggregate cost exceeds \$1,000.
- The Board of Directors will implement and/or continue preventive maintenance and repair programs to prevent abnormal deterioration of the common areas.
- The analysis assumes that no unusual conditions will occur, such as weather, vandalism, unusual use, or unforeseen obsolescence.
- Measurements and quantities were obtained by count, measurement, or estimation from plans
  provided by the Board of Directors unless otherwise noted, and are assumed to be a close
  approximation to actual.
- Proper construction and installation of all improvements is assumed, unless otherwise noted.
- This analysis assumes that the Association membership wishes to continue the use and maintenance of all amenities currently in place.
- The Association carries comprehensive property insurance to cover most insurable property risks.
- Current financial information was supplied by the Board of Directors and is assumed to be reasonably
  accurate as of the date of this analysis. Funded cash balances were not audited nor confirmed directly
  with financial institutions as a part of this analysis.
- The Association will collect and set aside reserve assessments on an annual basis as set forth in the funding plan projection, in order that sufficient funds will be available when expenditures are scheduled or necessary.
- The Board of Directors does not anticipate any special assessments other than those that may be scheduled as part of the attached 30-year funding projection.
- Interest rate of 2.00% is used in the funding plan.
- Inflation rate of 3.00% is used in the funding plan.



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Supplementary Information on Future Major Repairs and Replacements

		Estimated	Estimated
	Estimated	Remaining	Future
	Useful Lives	Useful Lives	Replacement
Category	Life YY:MM	Life YY:MM	Cost
Equipment	10:00 -15:00	1:00 - 4:00	\$ 31,855
Fitness	4:00	1:00	7,725
Flooring	30:00	18:00 -29:00	86,129
Furniture	5:00 -25:00	0:00 -23:00	52,667
HVAC	15:00	1:00 -14:00	49,239
Irrigation	20:00	10:00	6,720
Lakes	15:00 -50:00	5:00 -15:00	13,586
Lighting	10:00	5:00	5,796
Painting	10:00	1:00	24,720
Pavement	2:00 -20:00	1:00 - 9:00	314,933
Pool	10:00 -35:00	0:00 -15:00	108,475
Remodel	10:00 -25:00	1:00 -13:00	103,976
Roof	12:00 -25:00	6:00 -20:00	154,101
Safety/Security	12:00 -15:00	0:00 - 4:00	45,251
Sewer	5:00	1:00 - 5:00	166,093
Walls, Gates, Fence	5:00 -40:00	0:00 -24:00	189,762
Windows, Doors	10:00	5:00	5,796
		_	1,366,822



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Component List - Detail

Component		Service				Est	Adj	Rem	
Location	Desc.	Date	Basis Cost	Quantity	Current Cost	Life	Life	Life	Future Cost
Asphalt - Overlay									
Community		01/01/2011	\$ 12.00	17,500 Sq Yds	\$ 210,000	20:00	20:00	6:00	\$ 250,751
, ,				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	210,000				250,751
Asphalt - Repair & Re	eseal								
Community	Streets	01/01/2021	\$ 1.00	15,000 Sq Yds	\$ 15,000	5:00	5:00	1:00	\$ 15,450
Community	Parking Lot	01/01/2024	1.00	2,500 Sq Yds	2,500	5:00	5:00	4:00	2,814
					17,500				18,264
Audio/Visual Equipm	nent - Replace								
Clubhouse		01/01/2011	\$ 20,000.00	1 Allow	\$ 20,000	15:00	15:00	1:00	\$ 20,600
					20,000				20,600
Billiard Table - Refur	bish								
Clubhouse	Billiards	01/01/2024	\$ 1,000.00	3 Each	\$ 3,000	5:00	5:00	4:00	\$ 3,377
					3,000				3,377
Bldg Exterior - Repair	nt								
Clubhouse		01/01/2016	\$ 24,000.00	1 Job	\$ 24,000	10:00	10:00	1:00	\$ 24,720
					24,000				24,720
Bldg Exterior Gutters	s - Replace								
Clubhouse		01/01/2019	\$ 2,000.00	1 Allow	\$ 2,000	12:00	12:00	6:00	\$ 2,388
					2,000				2,388
Bldg Exterior Roof - F	Replace								
Clubhouse		01/01/2020	\$ 600.00	140 Squares	\$ 84,000	25:00	25:00	20:00	\$ 151,713
					84,000				151,713
Concrete - Partial Re	place								
Community		01/01/2024	\$ 12,000.00	1 Allow	\$ 12,000	2:00	2:00	1:00	\$ 12,360
					12,000				12,360

eport
Ignificant Assumptions

Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Detail

Component		Service				Est	Adj	Rem	
Location	Desc.	Date	Basis Cost	Quantity	Current Cost	Life	Life _	Life	Future Cost
Defibrillators - Repl	aco								
Clubhouse	acc	01/01/2017	\$ 2,000.00	1 Each	\$ 2,000	12:00	12:00	4:00	\$ 2,251
Clabilouse		01/01/2017	Ψ 2,000.00	i Lacii	2,000	12.00	12.00	4.00	2,251
Doors - Partial Repla	ace				2,000				2,231
Clubhouse		01/01/2020	\$ 2,500.00	1 Allow	\$ 2,500	10:00	10:00	5:00	\$ 2,898
			. ,		2,500				2,898
Entry FOB System -	Replace				,,,,,				,
Clubhouse		01/01/2010	\$ 22,000.00	1 Job	\$ 22,000	15:00	15:00	0:00	\$ 22,000
					22,000				22,000
Exhaust Fan - Repla	ce								
Pool		01/01/2005	\$ 2,000.00	1 Job	\$ 2,000	35:00	35:00	15:00	\$ 3,116
					2,000				3,116
Fence Metal - Repla	ace								
Community	Perimeter	01/01/2002	\$ 80.00	80 LF	\$ 6,400	40:00	40:00	17:00	\$ 10,578
					6,400				10,578
Fence Vinyl - Replac	e								
Community		01/01/2024	\$ 93.00	730 LF	\$ 67,890	25:00	25:00	24:00	\$ 138,006
					67,890				138,006
Fitness Equipment -	Replace								
Clubhouse		01/01/2022	\$ 7,500.00	1 Allow	\$ 7,500	4:00	4:00	1:00	\$ 7,725
					7,500				7,725
Flooring LVT - Repla	ice								
Clubhouse		01/01/2024	\$ 22,100.00	1 Job	\$ 22,100	30:00	30:00	29:00	\$ 52,080
					22,100				52,080
Flooring Tile - Repla	ce								
Clubhouse	Meeting Rm	01/01/2013	\$ 20,000.00	1 Job	\$ 20,000	30:00	30:00	18:00	\$ 34,049

PRN:06/28/2025

See Preparer's Report



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Detail

Component		Service				Est	Adj	Rem	
Location	Desc.	Date	Basis Cost	Quantity	Current Cost	Life	Life	Life	Future Cost
Fountain - Refurbish	า								
					20,000				34,049
Community		01/01/2019	\$ 10,000.00	1 Allow	\$ 10,000	10:00	10:00	4:00	\$ 11,255
j					10,000				11,255
Furniture Chairs - Ro	eplace								
Clubhouse	Auditorium	01/01/2019	\$ 2,000.00	1 Allow	\$ 2,000	25:00	25:00	19:00	\$ 3,507
					2,000				3,507
Furniture Poker Tab	le - Replace								
Clubhouse	Billiards	01/01/2015	\$ 2,500.00	1 Allow	\$ 2,500	20:00	20:00	10:00	\$ 3,360
					2,500				3,360
Furniture Tables - R	eplace								
Clubhouse	Auditorium	01/01/2023	\$ 2,500.00	1 Allow	\$ 2,500	25:00	25:00	23:00	\$ 4,934
					2,500				4,934
Gate Metal - Replac	e								
Pool		01/01/2013	\$ 500.00	2 Each	\$ 1,000	30:00	30:00	18:00	\$ 1,702
					1,000				1,702
Gazebo - Refurbish									
Community		01/01/2024	\$ 4,250.00	1 Allow	\$ 4,250	5:00	5:00	4:00	\$ 4,783
					4,250				4,783
HVAC 3-Ton - Repla									
Clubhouse	G028112	01/01/2020	\$ 5,000.00	1 Each	\$ 5,000	15:00	15:00	10:00	\$ 6,720
					5,000				6,720
HVAC 4-Ton - Repla									
Clubhouse	ICP-E112914913	01/01/2012	\$ 6,500.00	1 Each	\$ 6,500	15:00	15:00	2:00	\$ 6,896
Clubhouse	D - 2401072734	01/01/2024	6,500.00	1 Each	6,500	15:00	15:00	14:00	9,832

PRN:06/28/2025

See Preparer's Report



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Detail

Component		Service				Est	Adj	Rem	
Location	Desc.	Date	Basis Cost	Quantity	Current Cost	Life	Life	Life	Future Cost
HVAC 4-Ton - Repla	ce								
Clubhouse	ICP-E104601442	01/01/2011	\$ 6,500.00	1 Each	\$ 6,500	15:00	15:00	1:00	\$ 6,695
					19,500				23,423
HVAC 5-Ton - Repla	ce								
Clubhouse	E113906476	01/01/2012	\$ 9,000.00	1 Each	\$ 9,000	15:00	15:00	2:00	\$ 9,548
Clubhouse	E113801932	01/01/2012	9,000.00	1 Each	9,000	15:00	15:00	2:00	9,548
					18,000				19,096
Irrigation System - F	Repairs								
Community		01/01/2015	\$ 5,000.00	1 Allow	\$ 5,000	20:00	20:00	10:00	\$ 6,720
					5,000				6,720
Lake - Dredge & Sho	oreline Remediation								
Community		01/01/1990	\$ 5,000.00	1 Allow	\$ 5,000	50:00	50:00	15:00	\$ 7,790
					5,000				7,790
Lake Controller - Re	place								
Community		01/01/2015	\$ 5,000.00	1 Job	\$ 5,000	15:00	15:00	5:00	\$ 5,796
					5,000				5,796
Lighting - Replace									
Community		01/01/2020	\$ 5,000.00	1 Allow	\$ 5,000	10:00	10:00	5:00	\$ 5,796
,					5,000				5,796
Paver - Repair & Res	seal								
Pool	Pool	01/01/2021	\$ 2.95	3,650 Sq Ft	\$ 10,768	5:00	5:00	1:00	\$ 11,091
Clubhouse	Entry	01/01/2023	2.95	3,300 Sq Ft	9,735	5:00	5:00	3:00	10,638
	Š			·	20,503				21,728
Pool - Resurface									
Pool		01/01/2010	\$ 43,000.00	1 Job	\$ 43,000	15:00	15:00	0:00	\$ 43,000
					43,000				43,000
									,

See Preparer's Report
See Disclosures and Summary of Significant Assumptions
Page 27 of 104



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Detail

Component		Service				Est	Adj	Rem	
Location	Desc.	Date	Basis Cost	Quantity	Current Cost	Life	Life	Life	Future Cost
Pool Chlorination - F	Replace								
Pool		01/01/2021	\$ 3,500.00	1 Job	\$ 3,500	10:00	10:00	6:00	\$ 4,179
					3,500				4,179
Pool Filter - Replace									
Pool	2012 - I07SB017	01/01/2012	\$ 1,750.00	1 Each	\$ 1,750	15:00	15:00	2:00	\$ 1,857
Pool	2012 - I06SI030	01/01/2012	1,750.00	1 Each	1,750	15:00	15:00	2:00	1,857
					3,500				3,713
Pool Furniture - Rep	lace								
Pool		01/01/2019	\$ 12,000.00	1 Allow	\$ 12,000	10:00	10:00	4:00	\$ 13,506
					12,000				13,506
Pool Heater - Replace	ce								
Pool	181100379	01/01/2018	\$ 8,500.00	1 Each	\$ 8,500	12:00	12:00	5:00	\$ 9,854
Pool	181100376	01/01/2018	8,500.00	1 Each	8,500	12:00	12:00	5:00	9,854
Pool	181101520	01/01/2018	8,500.00	1 Each	8,500	12:00	12:00	5:00	9,854
Pool	181101524	01/01/2018	8,500.00	1 Each	8,500	12:00	7:00	0:00	8,500
					34,000				38,061
Pool Sauna - Refurbi	ish								
Clubhouse		01/01/2020	\$ 2,500.00	1 Allow	\$ 2,500	10:00	10:00	5:00	\$ 2,898
					2,500				2,898
Remodel Auditoriun	n - Remodel								
Clubhouse	Auditorium	01/01/2020	\$ 10,000.00	1 Allow	\$ 10,000	10:00	10:00	5:00	\$ 11,593
Clubhouse	Laundry Rm	01/01/2023	10,000.00	0.5 Allow	5,000	10:00	10:00	8:00	6,334
					15,000				17,927
Remodel Billiard Rm	n - Remodel								
Clubhouse	Billiards	01/01/2020	\$ 2,000.00	1 Allow	\$ 2,000	10:00	10:00	5:00	\$ 2,319
					2,000				2,319

Page 28 of 104

PRN:06/28/2025 See Preparer's Report
See Disclosures and Summary of Significant Assumptions

7

Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Detail

Component		Service				Est	Adj	Rem	
Location	Desc.	Date	Basis Cost	Quantity	Current Cost	Life	Life	Life	Future Cost
Remodel Clubhouse	Restrooms - Remode	el							
Clubhouse		01/01/2013	\$ 40,000.00	1 Allow	\$ 40,000	25:00	25:00	13:00	\$ 58,741
					40,000				58,741
Remodel Kitchen - R	emodel								
Clubhouse	Kitchen	01/01/2016	\$ 5,000.00	1 Allow	\$ 5,000	10:00	10:00	1:00	\$ 5,150
					5,000				5,150
Remodel Meeting R	m - Remodel								
Clubhouse	Meeting Rm	01/01/2017	\$ 18,700.00	1 Allow	\$ 18,700	10:00	10:00	2:00	\$ 19,839
					18,700				19,839
Security System - Re	place								
Community		01/01/2010	\$ 21,000.00	1 Allow	\$ 21,000	15:00	15:00	0:00	\$ 21,000
					21,000				21,000
Sewer Line - Repairs	;								
Community		01/01/2021	\$ 150,000.00	1 Allow	\$ 150,000	5:00	5:00	1:00	\$ 154,500
					150,000				154,500
Shuffleboard - Resul	rface								
Clubhouse	50% - 2022	01/01/2022	\$ 5,000.00	1 Job	\$ 5,000	12:00	12:00	9:00	\$ 6,524
Clubhouse	50% - 2027	01/01/2015	5,000.00	1 Job	5,000	12:00	12:00	2:00	5,305
					10,000				11,828
Shuffleboard Bench	es Wood - Repair & R	Replace							
Clubhouse		01/01/2021	\$ 2,500.00	1 Allow	\$ 2,500	5:00	5:00	1:00	\$ 2,575
					2,500				2,575
Shuffleboard Shade	Structures - Refurbis	h							
Clubhouse	SOUTH	01/01/1990	\$ 12.50	950 Sq Ft	\$ 11,875	35:00	35:00	0:00	\$ 11,875
Clubhouse	NORTH	01/01/1991	12.50	950 Sq Ft	11,875	35:00	37:00	3:00	12,976
					23,750				24,851

Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Detail

Component		Service				Est	Adj	Rem	
Location	Desc.	Date	Basis Cost	Quantity	Current Cost	Life	Life	Life	Future Cost
Signage Monument -	Refurbish								
Community		01/01/2023	\$ 12,500.00	1 Allow	\$ 12,500	15:00	15:00	13:00	\$ 18,357
					12,500				18,357
Signage Streets/Misc	- Repair & Replace	2							
Community		01/01/2020	\$ 8,000.00	1 Allow	\$ 8,000	10:00	10:00	5:00	\$ 9,274
					8,000				9,274
Storm Water Drainag	je - Repairs								
Community		01/01/2025	\$ 10,000.00	1 Allow	\$ 10,000	5:00	5:00	5:00	\$ 11,593
					10,000				11,593
Wall Block - Repair									
Community		01/01/2020	\$ 45.00	325 LF	\$ 14,625	5:00	5:00	0:00	\$ 14,625
					14,625				14,625
Windows - Partial Re	place								
Clubhouse		01/01/2020	\$ 2,500.00	1 Allow	\$ 2,500	10:00	10:00	5:00	\$ 2,898
					2,500				2,898
Windscreen - Replace	e								
Clubhouse		01/01/2015	\$ 2,500.00	1 Allow	\$ 2,500	10:00	10:00	0:00	\$ 2,500
					2,500				2,500
					1,066,718			_	1,366,822



# Supplementary Schedules Reserve Management Plan

# Type 2 - Reserve Study Update with On-Site Analysis

For 30-Year Projection Period Beginning January 1, 2025



Attached exhibits consist of component level detail reports. These reports are intended to supplement, but not be a part of the reserve study as of this same date.





Preparer's Report on Supplemental Information

Type 2 - Reserve Management Plan Reserve Study Update with On-Site Analysis

For 30-Year Projection Period Beginning January 1, 2025

Board of Directors Springwood Villas 2 Pinellas Park, FL

Report on Supplementary Information

The Supplementary Schedules as listed in the table of contents are presented for purposes of additional analysis and are not a required part of the financial projection. Such information is the responsibility of the Springwood Villas 2's management and was derived from the underlying component list used to prepare the basic reserve study report. The information has been subjected to the inquiry and other procedures applied in the compilation of the basic reserve study report, and we are not aware of any material modifications that should be made thereto.

Facilities Advisors Florida Greg Libke, RS, CAM June 28, 2025



Analysis Date - January 1, 2025

Inflation: 3.00% Investment: 2.00% Contribution Factor: 0.00% Calc: Future

# Percent Funded - Annual - Ending Balance

	Beginning		Percent		Expenditure	Ending	Percent	100 % Funded
Period	Balance	Contribution	Change	Interest	Future Cost	Balance	Funded	Time Value
1/25 - 12/25	\$ 719,661	\$ 52,585	0.00 %	\$ 12,667	\$ 123,500	\$ 661,413	101.78%	\$ 649,782
1/26 - 12/26	661,413	81,506	55.00	9,126	260,866	491,180	96.81	507,333
1/27 - 12/27	491,180	85,582	5.00	9,714	54,849	531,627	92.29	576,010
1/28 - 12/28	531,627	89,861	5.00	10,924	36,727	595,686	89.07	668,733
1/29 - 12/29	595,686	94,354	5.00	12,238	37,986	664,292	86.68	766,338
1/30 - 12/30	664,292	99,071	5.00	12,004	124,187	651,179	83.31	781,584
1/31 - 12/31	651,179	104,025	5.00	5,099	470,179	290,124	65.26	444,521
1/32 - 12/32	290,124	109,226	5.00	6,467	25,212	380,605	68.04	559,375
1/33 - 12/33	380,605	114,688	5.00	8,475	18,666	485,102	70.48	688,242
1/34 - 12/34	485,102	120,422	5.00	10,139	44,688	570,974	71.54	798,111
1/35 - 12/35	570,974	126,443	5.00	11,767	53,253	655,931	72.35	906,513
1/36 - 12/36	655,931	132,765	5.00	8,706	303,518	493,885	64.59	764,573
1/37 - 12/37	493,885	139,404	5.00	10,855	26,662	617,483	68.01	907,841
1/38 - 12/38	617,483	146,374	5.00	11,615	120,031	655,440	68.01	963,671
1/39 - 12/39	655,440	153,692	5.00	13,262	78,277	744,118	69.62	1,068,749
1/40 - 12/40	744,118	161,377	5.00	11,759	252,585	664,669	66.32	1,002,145
1/41 - 12/41	664,669	169,446	5.00	8,596	337,418	505,293	59.37	851,011
1/42 - 12/42	505,293	177,918	5.00	9,451	131,236	561,426	61.51	912,700
1/43 - 12/43	561,426	186,814	5.00	11,969	64,241	695,968	66.25	1,050,384
1/44 - 12/44	695,968	196,155	5.00	15,215	41,646	865,692	70.91	1,220,767
1/45 - 12/45	865,692	205,962	5.00	15,490	209,735	877,410	71.41	1,228,582
1/46 - 12/46	877,410	216,261	5.00	11,243	446,968	657,945	65.93	997,898
1/47 - 12/47	657,945	227,074	5.00	14,871	35,831	864,059	72.63	1,189,549
1/48 - 12/48	864,059	238,427	5.00	18,914	47,830	1,073,570	77.76	1,380,550
1/49 - 12/49	1,073,570	250,349	5.00	20,271	202,548	1,141,642	80.16	1,424,059
1/50 - 12/50	1,141,642	262,866	5.00	22,383	170,905	1,255,986	83.30	1,507,787
1/51 - 12/51	1,255,986	276,009	5.00	11,583	855,665	687,913	76.84	895,235
1/52 - 12/52	687,913	289,810	5.00	16,285	26,655	967,352	85.99	1,124,893
1/53 - 12/53	967,352	304,300	5.00	20,917	86,335	1,206,235	92.29	1,306,878
1/54 - 12/54	1,206,235	319,515	5.00	23,763	196,420	1,353,093	97.06	1,364,329

PRN:06/28/2025

See Preparer's Report






Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Percent Funded - Annual - Chart





# Springwood Villas 2 Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Expenditure - By Year

			Service	Estimated	
Date	Component	Location	Date	Life	Expenditure
Year: 2025					
01/01/2025	Entry FOB System - Replace	Clubhouse	01/01/2010	15:00	\$ 22,000.00
01/01/2025	Pool - Resurface	Pool	01/01/2010	15:00	43,000.00
01/01/2025	Pool Heater - Replace	Pool	01/01/2018	7:00	8,500.00
01/01/2025	Security System - Replace	Community	01/01/2010	15:00	21,000.00
01/01/2025	Shuffleboard Shade Structures - Refurbish	Clubhouse	01/01/1990	35:00	11,875.00
01/01/2025	Wall Block - Repair	Community	01/01/2020	5:00	14,625.00
01/01/2025	Windscreen - Replace	Clubhouse	01/01/2015	10:00	2,500.00
					123,500.00
Year : 2026					
01/01/2026	Asphalt - Repair & Reseal	Community	01/01/2021	5:00	\$ 15,450.00
01/01/2026	Audio/Visual Equipment - Replace	Clubhouse	01/01/2011	15:00	20,600.00
01/01/2026	Bldg Exterior - Repaint	Clubhouse	01/01/2016	10:00	24,720.00
01/01/2026	Concrete - Partial Replace	Community	01/01/2024	2:00	12,360.00
01/01/2026	Fitness Equipment - Replace	Clubhouse	01/01/2022	4:00	7,725.00
01/01/2026	HVAC 4-Ton - Replace	Clubhouse	01/01/2011	15:00	6,695.00
01/01/2026	Paver - Repair & Reseal	Pool	01/01/2021	5:00	11,090.53
01/01/2026	Remodel Kitchen - Remodel	Clubhouse	01/01/2016	10:00	5,150.00
01/01/2026	Sewer Line - Repairs	Community	01/01/2021	5:00	154,500.00
01/01/2026	Shuffleboard Benches Wood - Repair & Repl	Clubhouse	01/01/2021	5:00	2,575.00
	·				260,865.53
					200,000.00
Year: 2027					
	IN/AC 4 Ton Donloss	Clubhouse	01/01/2012	15.00	¢ 4 00E 0E
01/01/2027	HVAC 4-Ton - Replace HVAC 5-Ton - Replace	Clubhouse	01/01/2012 01/01/2012	15:00 15:00	\$ 6,895.85 9,548.10
01/01/2027	HVAC 5-Ton - Replace	Clubhouse	01/01/2012	15:00	9,548.10
01/01/2027	Pool Filter - Replace	Pool	01/01/2012	15:00	1,856.58
01/01/2027	·	Pool	01/01/2012	15:00	1,856.58
01/01/2027	Pool Filter - Replace Remodel Meeting Rm - Remodel	Clubhouse	01/01/2012	10:00	19,838.83
01/01/2027	Shuffleboard - Resurface	Clubhouse	01/01/2017	12:00	5,304.50
01/01/2027	Silumeboara - Resurrace	Ciubiliouse	01/01/2015	12.00	
					54,848.54
Year: 2028					
01/01/2028	Concrete - Partial Replace	Community	01/01/2026	2:00	\$ 13,112.72
01/01/2028	Paver - Repair & Reseal	Clubhouse	01/01/2023	5:00	10,637.70
01/01/2028	Shuffleboard Shade Structures - Refurbish	Clubhouse	01/01/1991	37:00	12,976.13
					36,726.55



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Expenditure - By Year

Data	Commonst	Lagation	Service	Estimated	Fun an ditura
Date	Component	Location	<u>Date</u>	Life	Expenditure
Year: 2029					
01/01/2029	Asphalt - Repair & Reseal	Community	01/01/2024	5:00	\$ 2,813.77
01/01/2029	Billiard Table - Refurbish	Clubhouse	01/01/2024	5:00	3,376.53
01/01/2029	Defibrillators - Replace	Clubhouse	01/01/2017	12:00	2,251.02
01/01/2029	Fountain - Refurbish	Community	01/01/2019	10:00	11,255.09
01/01/2029	Gazebo - Refurbish	Community	01/01/2024	5:00	4,783.41
01/01/2029	Pool Furniture - Replace	Pool	01/01/2019	10:00	13,506.11
					37,985.93
Year: 2030					
01/01/2030	Concrete - Partial Replace	Community	01/01/2028	2:00	\$ 13,911.29
01/01/2030	Doors - Partial Replace	Clubhouse	01/01/2020	10:00	2,898.19
01/01/2030	Fitness Equipment - Replace	Clubhouse	01/01/2026	4:00	8,694.56
01/01/2030	Lake Controller - Replace	Community	01/01/2015	15:00	5,796.37
01/01/2030	Lighting - Replace	Community	01/01/2020	10:00	5,796.37
01/01/2030	Pool Heater - Replace	Pool	01/01/2018	12:00	9,853.83
01/01/2030	Pool Heater - Replace	Pool	01/01/2018	12:00	9,853.83
01/01/2030	Pool Heater - Replace	Pool	01/01/2018	12:00	9,853.83
01/01/2030	Pool Sauna - Refurbish	Clubhouse	01/01/2020	10:00	2,898.19
01/01/2030	Remodel Auditorium - Remodel	Clubhouse	01/01/2020	10:00	11,592.74
01/01/2030	Remodel Billiard Rm - Remodel	Clubhouse	01/01/2020	10:00	2,318.55
01/01/2030	Signage Streets/Misc - Repair & Replace	Community	01/01/2020	10:00	9,274.19
01/01/2030	Storm Water Drainage - Repairs	Community	01/01/2025	5:00	11,592.74
01/01/2030	Wall Block - Repair	Community	01/01/2025	5:00	16,954.38
01/01/2030	Windows - Partial Replace	Clubhouse	01/01/2020	10:00	2,898.19
				_	124,187.25
Year : 2031					
01/01/2031	Asphalt - Overlay	Community	01/01/2011	20:00	\$ 250,750.98
01/01/2031	Asphalt - Repair & Reseal	Community	01/01/2026	5:00	17,910.78
01/01/2031	Bldg Exterior Gutters - Replace	Clubhouse	01/01/2019	12:00	2,388.10
01/01/2031	Paver - Repair & Reseal	Pool	01/01/2026	5:00	12,856.96
01/01/2031	Pool Chlorination - Replace	Pool	01/01/2021	10:00	4,179.18
01/01/2031	Sewer Line - Repairs	Community	01/01/2026	5:00	179,107.84
01/01/2031	Shuffleboard Benches Wood - Repair & Repl	Clubhouse	01/01/2026	5:00	2,985.13
				_	470,178.97
Year: 2032					
01/01/2032	Concrete - Partial Replace	Community	01/01/2030	2:00	\$ 14,758.49
01/01/2032	Pool Heater - Replace	Pool	01/01/2025	7:00	10,453.93
PRN:06/28/2025		Preparer's Report			

PRN:06/28/2025

See Preparer's Report

See Disclosures and Summary of Significant Assumptions

Page 36 of 104



# Springwood Villas 2 Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

			Service	Estimated	
Date	Component	Location	Date	Life	Expenditure
					25,212.42
Year: 2033					
01/01/2033	Paver - Repair & Reseal	Clubhouse	01/01/2028	5:00	\$ 12,332.01
01/01/2033	Remodel Auditorium - Remodel	Clubhouse	01/01/2023	10:00	6,333.85
01/01/2033	Remodel Additionally - Remodel	Clubillouse	01/01/2023		18,665.86
					10,000.00
V 2024					
Year: 2034			04 (04 (0000	5.00	<b>*</b> 0 0 / 1 00
01/01/2034	Asphalt - Repair & Reseal	Community	01/01/2029	5:00	\$ 3,261.93
01/01/2034	Billiard Table - Refurbish	Clubhouse	01/01/2029	5:00	3,914.32
01/01/2034	Concrete - Partial Replace	Community	01/01/2032	2:00	15,657.28
01/01/2034	Fitness Equipment - Replace	Clubhouse	01/01/2030	4:00	9,785.80
01/01/2034	Gazebo - Refurbish	Community	01/01/2029	5:00	5,545.29
01/01/2034	Shuffleboard - Resurface	Clubhouse	01/01/2022	12:00	6,523.87
					44,688.49
Year: 2035					
01/01/2035	Furniture Poker Table - Replace	Clubhouse	01/01/2015	20:00	\$ 3,359.79
01/01/2035	HVAC 3-Ton - Replace	Clubhouse	01/01/2020	15:00	6,719.58
01/01/2035	Irrigation System - Repairs	Community	01/01/2015	20:00	6,719.58
01/01/2035	Storm Water Drainage - Repairs	Community	01/01/2030	5:00	13,439.16
01/01/2035	Wall Block - Repair	Community	01/01/2030	5:00	19,654.78
01/01/2035	Windscreen - Replace	Clubhouse	01/01/2025	10:00	3,359.79
				_	53,252.68
					,
Year : 2036					
01/01/2036	Asphalt - Repair & Reseal	Community	01/01/2031	5:00	\$ 20,763.51
01/01/2036	Bldg Exterior - Repaint	Clubhouse	01/01/2031	10:00	33,221.61
	Concrete - Partial Replace				
01/01/2036	•	Community Pool	01/01/2034 01/01/2031	2:00 5:00	16,610.81
01/01/2036	Paver - Repair & Reseal		01/01/2031		14,904.74
01/01/2036	Remodel Kitchen - Remodel	Clubhouse		10:00	6,921.17
01/01/2036	Sewer Line - Repairs	Community	01/01/2031	5:00	207,635.08
01/01/2036	Shuffleboard Benches Wood - Repair & Repl	Clubhouse	01/01/2031	5:00	3,460.58
					303,517.50
Year: 2037					
01/01/2037	Remodel Meeting Rm - Remodel	Clubhouse	01/01/2027	10:00	\$ 26,661.73
					26,661.73



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

## Expenditure - By Year

			Service	Estimated	
Date	Component	Location	Date	Life	Expenditure
		•		-	_
Year: 2038					
01/01/2038	Concrete - Partial Replace	Community	01/01/2036	2:00	\$ 17,622.40
01/01/2038	Fitness Equipment - Replace	Clubhouse	01/01/2034	4:00	11,014.00
01/01/2038	Paver - Repair & Reseal	Clubhouse	01/01/2033	5:00	14,296.18
01/01/2038	Remodel Clubhouse Restrooms - Remodel	Clubhouse	01/01/2013	25:00	58,741.35
01/01/2038	Signage Monument - Refurbish	Community	01/01/2023	15:00	18,356.67
					120,030.60
Year: 2039					
01/01/2039	Asphalt - Repair & Reseal	Community	01/01/2034	5:00	\$ 3,781.47
01/01/2039	Billiard Table - Refurbish	Clubhouse	01/01/2034	5:00	4,537.77
01/01/2039	Fountain - Refurbish	Community	01/01/2029	10:00	15,125.90
01/01/2039	Gazebo - Refurbish	Community	01/01/2034	5:00	6,428.51
01/01/2039	HVAC 4-Ton - Replace	Clubhouse	01/01/2024	15:00	9,831.83
01/01/2039	Pool Furniture - Replace	Pool	01/01/2029	10:00	18,151.08
01/01/2039	Pool Heater - Replace	Pool	01/01/2032	7:00	12,857.01
01/01/2039	Shuffleboard - Resurface	Clubhouse	01/01/2027	12:00	7,562.95
					78,276.52
					•
Year: 2040					
01/01/2040	Concrete - Partial Replace	Community	01/01/2038	2:00	\$ 18,695.61
01/01/2040	Doors - Partial Replace	Clubhouse	01/01/2030	10:00	3,894.92
01/01/2040	Entry FOB System - Replace	Clubhouse	01/01/2030	15:00	34,275.28
01/01/2040	Exhaust Fan - Replace	Pool	01/01/2025	35:00	3,115.93
01/01/2040	Lake - Dredge & Shoreline Remediation	Community	01/01/1990	50:00	7,789.84
01/01/2040	Lighting - Replace	Community	01/01/2030	10:00	7,789.84
01/01/2040	Pool - Resurface	Pool	01/01/2035	15:00	66,992.60
01/01/2040	Pool Sauna - Refurbish	Clubhouse	01/01/2030	10:00	3,894.92
01/01/2040	Remodel Auditorium - Remodel	Clubhouse	01/01/2030	10:00	15,579.67
01/01/2040	Remodel Billiard Rm - Remodel	Clubhouse	01/01/2030	10:00	3,115.93
01/01/2040	Security System - Replace	Community	01/01/2025	15:00	32,717.32
01/01/2040	Signage Streets/Misc - Repair & Replace	Community	01/01/2030	10:00	12,463.74
01/01/2040	Storm Water Drainage - Repairs	Community	01/01/2035	5:00	15,579.67
01/01/2040	Wall Block - Repair	Community	01/01/2035	5:00	22,785.27
01/01/2040	Windows - Partial Replace	Clubhouse	01/01/2030	10:00	3,894.92
01/01/2010	William Variation Replace	oldbilod30	0170172000		252,585.46
					232,303.40
V 2041					
Year: 2041		_			
01/01/2041	Asphalt - Repair & Reseal	Community	01/01/2036	5:00	\$ 24,070.60
01/01/2041	Audio/Visual Equipment - Replace	Clubhouse	01/01/2026	15:00	32,094.13
PRN:06/28/2025	See	Preparer's Report			

See Preparer's Report

See Disclosures and Summary of Significant Assumptions

Page 38 of 104



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

			Service	Estimated	
Date	Component	Location	Date	Life	Expenditure
04 /04 /00 44	D (1) 111	01.11	04 (04 (0000	10.00	<b>*</b> 0 000 44
01/01/2041	Defibrillators - Replace	Clubhouse	01/01/2029	12:00	\$ 3,209.41
01/01/2041	HVAC 4-Ton - Replace	Clubhouse	01/01/2026	15:00	10,430.59
01/01/2041	Paver - Repair & Reseal	Pool	01/01/2036	5:00	17,278.68
01/01/2041	Pool Chlorination - Replace	Pool	01/01/2031	10:00	5,616.47
01/01/2041	Sewer Line - Repairs	Community	01/01/2036	5:00	240,705.97
01/01/2041	Shuffleboard Benches Wood - Repair & Repl	Clubhouse	01/01/2036	5:00	4,011.77
					337,417.62
Year : 2042					
	Concrete Partial Penlage	Community	01/01/2040	2.00	¢ 10 024 17
01/01/2042	Concrete - Partial Replace	Community	01/01/2040	2:00	\$ 19,834.17
01/01/2042	Fence Metal - Replace	Community	01/01/2002	40:00	10,578.22
01/01/2042	Fitness Equipment - Replace	Clubhouse	01/01/2038	4:00	12,396.36
01/01/2042	HVAC 5 Tan Replace	Clubhouse	01/01/2027	15:00	10,743.51
01/01/2042	HVAC 5-Ton - Replace	Clubhouse	01/01/2027	15:00	14,875.63
01/01/2042	HVAC 5-Ton - Replace	Clubhouse	01/01/2027	15:00	14,875.63
01/01/2042	Pool Filter - Replace	Pool	01/01/2027	15:00	2,892.48
01/01/2042	Pool Filter - Replace	Pool	01/01/2027	15:00	2,892.48
01/01/2042	Pool Heater - Replace	Pool	01/01/2030	12:00	14,049.20
01/01/2042	Pool Heater - Replace	Pool	01/01/2030	12:00	14,049.20
01/01/2042	Pool Heater - Replace	Pool	01/01/2030	12:00	14,049.20
					131,236.08
Year: 2043					
01/01/2043	Bldg Exterior Gutters - Replace	Clubhouse	01/01/2031	12:00	\$ 3,404.87
01/01/2043	Flooring Tile - Replace	Clubhouse	01/01/2013	30:00	34,048.66
01/01/2043	Gate Metal - Replace	Pool	01/01/2013	30:00	1,702.43
01/01/2043	Paver - Repair & Reseal	Clubhouse	01/01/2038	5:00	16,573.19
01/01/2043	Remodel Auditorium - Remodel	Clubhouse	01/01/2033	10:00	8,512.17
				_	64,241.32
Year: 2044					
01/01/2044	Asphalt - Repair & Reseal	Community	01/01/2039	5:00	\$ 4,383.77
01/01/2044	Billiard Table - Refurbish	Clubhouse	01/01/2039	5:00	5,260.52
01/01/2044	Concrete - Partial Replace	Community	01/01/2042	2:00	21,042.07
01/01/2044	Furniture Chairs - Replace	Clubhouse	01/01/2019	25:00	3,507.01
01/01/2044	Gazebo - Refurbish	Community	01/01/2039	5:00	7,452.40
					41,645.77



# Springwood Villas 2 Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

			Service	Estimated	
Date	Component	Location	Date	Life	Expenditure
Year: 2045					
01/01/2045	Bldg Exterior Roof - Replace	Clubhouse	01/01/2020	25:00	\$ 151,713.34
01/01/2045	Lake Controller - Replace	Community	01/01/2030	15:00	9,030.56
01/01/2045	Storm Water Drainage - Repairs	Community	01/01/2040	5:00	18,061.11
01/01/2045	Wall Block - Repair	Community	01/01/2040	5:00	26,414.38
01/01/2045	Windscreen - Replace	Clubhouse	01/01/2035	10:00	4,515.28
					209,734.67
Year : 2046					
01/01/2046	Asphalt - Repair & Reseal	Community	01/01/2041	5:00	\$ 27,904.42
01/01/2046	Bldg Exterior - Repaint	Clubhouse	01/01/2036	10:00	44,647.07
01/01/2046	Concrete - Partial Replace	Community	01/01/2044	2:00	22,323.53
01/01/2046	Fitness Equipment - Replace	Clubhouse	01/01/2042	4:00	13,952.21
01/01/2046	Paver - Repair & Reseal	Pool	01/01/2041	5:00	20,030.72
01/01/2046	Pool Heater - Replace	Pool	01/01/2039	7:00	15,812.50
01/01/2046	Remodel Kitchen - Remodel	Clubhouse	01/01/2036	10:00	9,301.47
01/01/2046	Sewer Line - Repairs	Community	01/01/2041	5:00	279,044.19
01/01/2046	Shuffleboard - Resurface	Clubhouse	01/01/2034	12:00	9,301.47
01/01/2046	Shuffleboard Benches Wood - Repair & Repl	Clubhouse	01/01/2041	5:00	4,650.74
	'				446,968.32
					1.10/700.02
Year: 2047					
	Danie del Marakino Dire. Deve del	Olyala la accesa	01/01/0007	10.00	ф 2F 021 12
01/01/2047	Remodel Meeting Rm - Remodel	Clubhouse	01/01/2037	10:00	\$ 35,831.13
					35,831.13
Year: 2048					
01/01/2048	Concrete - Partial Replace	Community	01/01/2046	2:00	\$ 23,683.04
01/01/2048	Furniture Tables - Replace	Clubhouse	01/01/2023	25:00	4,933.97
01/01/2048	Paver - Repair & Reseal	Clubhouse	01/01/2043	5:00	19,212.86
					47,829.87
Year: 2049					
01/01/2049	Asphalt - Repair & Reseal	Community	01/01/2044	5:00	\$ 5,081.99
01/01/2049	Billiard Table - Refurbish	Clubhouse	01/01/2044	5:00	6,098.38
01/01/2049	Fence Vinyl - Replace	Community	01/01/2024	25:00	138,006.39
01/01/2049	Fountain - Refurbish	Community	01/01/2039	10:00	20,327.94
01/01/2049	Gazebo - Refurbish	Community	01/01/2044	5:00	8,639.37
01/01/2049	Pool Furniture - Replace	Pool	01/01/2039	10:00	24,393.53
	·				202,547.60
					_==_,= :: 100



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

			Service	Estimated	
Date	Component	Location	Date	Life	Expenditure
Year: 2050					
01/01/2050	Concrete - Partial Replace	Community	01/01/2048	2:00	\$ 25,125.34
01/01/2050	Doors - Partial Replace	Clubhouse	01/01/2040	10:00	5,234.44
01/01/2050	Fitness Equipment - Replace	Clubhouse	01/01/2046	4:00	15,703.33
01/01/2050	HVAC 3-Ton - Replace	Clubhouse	01/01/2035	15:00	10,468.89
01/01/2050	Lighting - Replace	Community	01/01/2040	10:00	10,468.89
01/01/2050	Pool Sauna - Refurbish	Clubhouse	01/01/2040	10:00	5,234.44
01/01/2050	Remodel Auditorium - Remodel	Clubhouse	01/01/2040	10:00	20,937.78
01/01/2050	Remodel Billiard Rm - Remodel	Clubhouse	01/01/2040	10:00	4,187.56
01/01/2050	Signage Streets/Misc - Repair & Replace	Community	01/01/2040	10:00	16,750.22
01/01/2050	Storm Water Drainage - Repairs	Community	01/01/2045	5:00	20,937.78
01/01/2050	Wall Block - Repair	Community	01/01/2045	5:00	30,621.50
01/01/2050	Windows - Partial Replace	Clubhouse	01/01/2040	10:00	5,234.44
				_	170,904.61
					,
Year: 2051					
	A 1 11 0 1	0 "	04 /04 /0004	22.22	<b># 450 004 17</b>
01/01/2051	Asphalt - Overlay	Community	01/01/2031	20:00	\$ 452,884.17
01/01/2051	Asphalt - Repair & Reseal	Community	01/01/2046	5:00	32,348.87
01/01/2051	Paver - Repair & Reseal	Pool	01/01/2046	5:00	23,221.10
01/01/2051	Pool Chlorination - Replace	Pool	01/01/2041	10:00	7,548.07
01/01/2051	Sewer Line - Repairs	Community	01/01/2046	5:00	323,488.69
01/01/2051	Shuffleboard - Resurface	Clubhouse	01/01/2039	12:00	10,782.96
01/01/2051	Shuffleboard Benches Wood - Repair & Repl	Clubhouse	01/01/2046	5:00	5,391.48
					855,665.34
Year: 2052					
01/01/2052	Concrete - Partial Replace	Community	01/01/2050	2:00	\$ 26,655.47
	·	,		<del>-</del>	26,655.47
					20,000.17
V 2052					
Year: 2053					
01/01/2053	Defibrillators - Replace	Clubhouse	01/01/2041	12:00	\$ 4,575.86
01/01/2053	Paver - Repair & Reseal	Clubhouse	01/01/2048	5:00	22,272.98
01/01/2053	Pool Heater - Replace	Pool	01/01/2046	7:00	19,447.39
01/01/2053	Remodel Auditorium - Remodel	Clubhouse	01/01/2043	10:00	11,439.64
01/01/2053	Signage Monument - Refurbish	Community	01/01/2038	15:00	28,599.10
					86,334.97



# Springwood Villas 2 Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

			Service	Estimated	
Date	Component	Location	Date	Life	Expenditure
Year: 2054					
01/01/2054	Asphalt - Repair & Reseal	Community	01/01/2049	5:00	\$ 5,891.41
01/01/2054	Billiard Table - Refurbish	Clubhouse	01/01/2049	5:00	7,069.70
01/01/2054	Concrete - Partial Replace	Community	01/01/2052	2:00	28,278.79
01/01/2054	Fitness Equipment - Replace	Clubhouse	01/01/2050	4:00	17,674.24
01/01/2054	Flooring LVT - Replace	Clubhouse	01/01/2024	30:00	52,080.10
01/01/2054	Gazebo - Refurbish	Community	01/01/2049	5:00	10,015.40
01/01/2054	HVAC 4-Ton - Replace	Clubhouse	01/01/2039	15:00	15,317.68
01/01/2054	Pool Heater - Replace	Pool	01/01/2042	12:00	20,030.81
01/01/2054	Pool Heater - Replace	Pool	01/01/2042	12:00	20,030.81
01/01/2054	Pool Heater - Replace	Pool	01/01/2042	12:00	20,030.81
				·	196,419.75



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

## Expenditure - By Component

		Service	Estimated		
Date	Location	Date	Life	Current Cost	Expenditure
Asphalt - Overlay					
01/01/2031	Community	01/01/2011	20:00	\$ 210,000.00	\$ 250,750.98
01/01/2051	Community	01/01/2031	20:00	210,000.00	452,884.17
01/01/2001	oommanity	01/01/2001		420,000.00	703,635.15
Asphalt - Repair & R	eseal				
01/01/2026	Community	01/01/2021	5:00	\$ 15,000.00	\$ 15,450.00
01/01/2029	Community	01/01/2024	5:00	2,500.00	2,813.77
01/01/2031	Community	01/01/2026	5:00	15,000.00	17,910.78
01/01/2034	Community	01/01/2029	5:00	2,500.00	3,261.93
01/01/2036	Community	01/01/2031	5:00	15,000.00	20,763.51
01/01/2039	Community	01/01/2034	5:00	2,500.00	3,781.47
01/01/2041	Community	01/01/2036	5:00	15,000.00	24,070.60
01/01/2044	Community	01/01/2039	5:00	2,500.00	4,383.77
01/01/2046	Community	01/01/2041	5:00	15,000.00	27,904.42
01/01/2049	Community	01/01/2044	5:00	2,500.00	5,081.99
01/01/2051	Community	01/01/2046	5:00	15,000.00	32,348.87
01/01/2054	Community	01/01/2049	5:00	2,500.00	5,891.41
	-		_	105,000.00	163,662.52
Audio/Visual Equipn	nent - Replace				
01/01/2026	Clubhouse	01/01/2011	15:00	\$ 20,000.00	\$ 20,600.00
01/01/2041	Clubhouse	01/01/2026	15:00	20,000.00	32,094.13
				40,000.00	52,694.13
Billiard Table - Refur	bish				
01/01/2029	Clubhouse	01/01/2024	5:00	\$ 3,000.00	\$ 3,376.53
01/01/2034	Clubhouse	01/01/2029	5:00	3,000.00	3,914.32
01/01/2039	Clubhouse	01/01/2034	5:00	3,000.00	4,537.77
01/01/2044	Clubhouse	01/01/2039	5:00	3,000.00	5,260.52
01/01/2049	Clubhouse	01/01/2044	5:00	3,000.00	6,098.38
01/01/2054	Clubhouse	01/01/2049	5:00	3,000.00	7,069.70
			_	18,000.00	30,257.22
Bldg Exterior - Repai	nt				
01/01/2026	Clubhouse	01/01/2016	10:00	\$ 24,000.00	\$ 24,720.00
01/01/2036	Clubhouse	01/01/2026	10:00	24,000.00	33,221.61
01/01/2046	Clubhouse	01/01/2036	10:00	24,000.00	44,647.07
				72,000.00	102,588.68
Bldg Exterior Gutters	s - Replace				
01/01/2031	Clubhouse	01/01/2019	12:00	\$ 2,000.00	\$ 2,388.10
DBN:06/29/2025			arar's Danart		

PRN:06/28/2025

See Preparer's Report

See Disclosures and Summary of Significant Assumptions

Page 43 of 104



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

### Expenditure - By Component

Date	Location	Service Date	Estimated Life	Current Cost	Expenditure
Date	Location			- Current cost	Experiantare
g Exterior Gutters	s - Replace				
01/01/2043	Clubhouse	01/01/2031	12:00	\$ 2,000.00	\$ 3,404.87
				4,000.00	5,792.97
g Exterior Roof - F	Replace				
01/01/2045	Clubhouse	01/01/2020	25:00	\$ 84,000.00	\$ 151,713.34
				84,000.00	151,713.34
ncrete - Partial Re	place				
01/01/2026	Community	01/01/2024	2:00	\$ 12,000.00	\$ 12,360.00
01/01/2028	Community	01/01/2026	2:00	12,000.00	13,112.72
01/01/2030	Community	01/01/2028	2:00	12,000.00	13,911.29
01/01/2032	Community	01/01/2030	2:00	12,000.00	14,758.49
01/01/2034	Community	01/01/2032	2:00	12,000.00	15,657.28
01/01/2036	Community	01/01/2034	2:00	12,000.00	16,610.8
01/01/2038	Community	01/01/2036	2:00	12,000.00	17,622.40
01/01/2040	Community	01/01/2038	2:00	12,000.00	18,695.6
01/01/2042	Community	01/01/2040	2:00	12,000.00	19,834.1
01/01/2044	Community	01/01/2042	2:00	12,000.00	21,042.0
01/01/2046	Community	01/01/2044	2:00	12,000.00	22,323.53
01/01/2048	Community	01/01/2046	2:00	12,000.00	23,683.04
01/01/2050	Community	01/01/2048	2:00	12,000.00	25,125.34
01/01/2052	Community	01/01/2050	2:00	12,000.00	26,655.47
01/01/2054	Community	01/01/2052	2:00	12,000.00	28,278.79
	,			180,000.00	289,671.01
ibrillators - Repla	ce				
01/01/2029	Clubhouse	01/01/2017	12:00	\$ 2,000.00	\$ 2,251.02
01/01/2041	Clubhouse	01/01/2029	12:00	2,000.00	3,209.41
01/01/2053	Clubhouse	01/01/2041	12:00	2,000.00	4,575.86
			_	6,000.00	10,036.29
ors - Partial Repla	ce				
01/01/2030	Clubhouse	01/01/2020	10:00	\$ 2,500.00	\$ 2,898.19
01/01/2040	Clubhouse	01/01/2030	10:00	2,500.00	3,894.92
01/01/2050	Clubhouse	01/01/2040	10:00	2,500.00	5,234.44
			_	7,500.00	12,027.55
ry FOB System - R	Replace				
01/01/2025	Clubhouse	01/01/2010	15:00	\$ 22,000.00	\$ 22,000.00
01/01/2040	Clubhouse	01/01/2025	15:00	22,000.00	34,275.28

PRN:06/28/2025

See Preparer's Report

See Disclosures and Summary of Significant Assumptions

Page 44 of 104



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

### Expenditure - By Component

Exhaust Fan - Replace  01/01/2040 Pool 01/01/2005 35:00 \$2,000.00 \$3,115:9  Fence Metal - Replace  01/01/2042 Community 01/01/2002 40:00 \$6,400.00 \$10,578:2  Fence Vinyl - Replace  01/01/2049 Community 01/01/2024 25:00 \$67,890.00 \$138,006:3  Fitness Equipment - Replace  01/01/2026 Clubhouse 01/01/2024 40:00 \$7,500.00 \$138,006:3  Fitness Equipment - Replace  01/01/2030 Clubhouse 01/01/2024 40:00 \$7,500.00 \$8,044:5  01/01/2030 Clubhouse 01/01/2026 40:00 \$7,500.00 \$8,044:5  01/01/2031 Clubhouse 01/01/2034 40:00 \$7,500.00 \$9,785.8  01/01/2032 Clubhouse 01/01/2034 40:00 \$7,500.00 \$138,006:3  01/01/2034 Clubhouse 01/01/2034 40:00 \$7,500.00 \$1,0	Date	Location	Service Date	Estimated Life	Current Cost	Expenditure
Mathematical Community   Mathematical Commun						· ·
O1/01/2040   Pool   O1/01/2005   35:00   \$2,000.00   \$3.115.9	Exhaust Fan - Replac	e				
Fence Metal - Replace 01/01/2042 Community 01/01/2002 40:00 \$6,400.00 \$10,578.2  Fence Vinyl - Replace 01/01/2049 Community 01/01/2024 25:00 \$67,890.00 \$138,006.3  Fitness Equipment - Replace 01/01/2030 Clubhouse 01/01/2024 4:00 \$7,500.00 \$7,725.0 01/01/2030 Clubhouse 01/01/2026 4:00 \$7,500.00 \$7,725.0 01/01/2034 Clubhouse 01/01/2030 4:00 7,500.00 9,785.8 01/01/2038 Clubhouse 01/01/2038 4:00 7,500.00 11,014.0 01/01/2042 Clubhouse 01/01/2038 4:00 7,500.00 12,396.3 01/01/2042 Clubhouse 01/01/2038 4:00 7,500.00 12,396.3 01/01/2046 Clubhouse 01/01/2038 4:00 7,500.00 12,396.3 01/01/2046 Clubhouse 01/01/2038 4:00 7,500.00 13,952.2 01/01/2050 Clubhouse 01/01/2042 4:00 7,500.00 13,952.2 01/01/2054 Clubhouse 01/01/2046 4:00 7,500.00 15,703.3 01/01/2054 Clubhouse 01/01/2046 4:00 7,500.00 15,703.5 01/01/2054 Clubhouse 01/01/2046 4:00 7,500.00 15,703.3 01/01/2054 Clubhouse 01/01/2046 4:00 7,500.00 15,700.00 15,703.3 01/01/2054 Clubhouse 01/01/2046 4:00 7,500.00 15,7000.00 15,7000.00 15,7000.00 15,7000.00 15,7000.00 15,7000.00 15,7000.00 15,7000.00					44,000.00	56,275.28
Fence Metal - Replace 01/01/2042 Community 01/01/2002 40:00 \$6,400.00 \$10,578.2  Fence Vinyl - Replace 01/01/2049 Community 01/01/2024 25:00 \$67,890.00 \$138,006.3  Fitness Equipment - Replace 01/01/2030 Clubhouse 01/01/2024 4:00 \$7,500.00 \$7,725.0 01/01/2030 Clubhouse 01/01/2026 4:00 \$7,500.00 \$7,725.0 01/01/2034 Clubhouse 01/01/2030 4:00 7,500.00 9,785.8 01/01/2038 Clubhouse 01/01/2038 4:00 7,500.00 11,014.0 01/01/2042 Clubhouse 01/01/2038 4:00 7,500.00 12,396.3 01/01/2042 Clubhouse 01/01/2038 4:00 7,500.00 12,396.3 01/01/2046 Clubhouse 01/01/2038 4:00 7,500.00 12,396.3 01/01/2046 Clubhouse 01/01/2038 4:00 7,500.00 13,952.2 01/01/2050 Clubhouse 01/01/2042 4:00 7,500.00 13,952.2 01/01/2054 Clubhouse 01/01/2046 4:00 7,500.00 15,703.3 01/01/2054 Clubhouse 01/01/2046 4:00 7,500.00 15,703.5 01/01/2054 Clubhouse 01/01/2046 4:00 7,500.00 15,703.3 01/01/2054 Clubhouse 01/01/2046 4:00 7,500.00 15,700.00 15,703.3 01/01/2054 Clubhouse 01/01/2046 4:00 7,500.00 15,7000.00 15,7000.00 15,7000.00 15,7000.00 15,7000.00 15,7000.00 15,7000.00 15,7000.00	01/01/2040	Dool	01/01/2005	25,00	¢ 2 000 00	¢ 2 11E 02
Fence Metal - Replace  01/01/2042	01/01/2040	POOI	01/01/2003	35.00		
O1/01/2042   Community   O1/01/2002   40:00   \$6,400.00   \$10,578.2					2,000.00	5,115.75
Fence Vinyl - Replace 01/01/2049 Community 01/01/2024 25:00 \$67,890.00 \$138,006.3  Fitness Equipment - Replace 01/01/2026 Clubhouse 01/01/2022 4:00 \$7,500.00 \$7,725.0 01/01/2030 Clubhouse 01/01/2030 4:00 7,500.00 9,785.8 01/01/2034 Clubhouse 01/01/2034 4:00 7,500.00 11,014.0 01/01/2042 Clubhouse 01/01/2034 4:00 7,500.00 13,952.2 01/01/2046 Clubhouse 01/01/2042 4:00 7,500.00 13,952.2 01/01/2050 Clubhouse 01/01/2046 4:00 7,500.00 15,703.3 01/01/2054 Clubhouse 01/01/2050 4:00 7,500.00 17,674.2 01/01/2054 Clubhouse 01/01/2050 4:00 7,500.00 17,674.2 Flooring LVT - Replace 01/01/2054 Clubhouse 01/01/2024 30:00 \$22,100.00 \$52,080.1  Flooring Tile - Replace 01/01/2043 Clubhouse 01/01/2013 30:00 \$22,100.00 \$34,048.6  Fountain - Refurbish 01/01/2029 Community 01/01/2019 10:00 \$10,000.00 \$11,255.0 01/01/2039 Community 01/01/2029 10:00 10,000.00 15,125.9 01/01/2049 Community 01/01/2029 10:00 10,000.00 15,125.9 01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9 01/01/2044 Clubhouse 01/01/2039 25:00 \$2,000.00 \$3,5	· ·					
Fence Vinyl - Replace 01/01/2049	01/01/2042	Community	01/01/2002	40:00	\$ 6,400.00	\$ 10,578.22
O1/01/2049   Community   O1/01/2024   25:00   \$67,890.00   \$138,006.3					6,400.00	10,578.22
O1/01/2049   Community   O1/01/2024   25:00   \$67,890.00   \$138,006.3	Fence Vinyl - Replace	ė				
Fitness Equipment - Replace  01/01/2026	• •		01/01/2024	25:00	\$ 67,890.00	\$ 138,006.39
01/01/2026 Clubhouse 01/01/2022 4:00 \$7,500.00 \$7,725.0   01/01/2030 Clubhouse 01/01/2036 4:00 7,500.00 8,694.5   01/01/2034 Clubhouse 01/01/2034 4:00 7,500.00 9,785.8   01/01/2038 Clubhouse 01/01/2038 4:00 7,500.00 11,014.0   01/01/2042 Clubhouse 01/01/2038 4:00 7,500.00 12,396.3   01/01/2046 Clubhouse 01/01/2044 4:00 7,500.00 13,952.2   01/01/2050 Clubhouse 01/01/2046 4:00 7,500.00 13,752.2   01/01/2054 Clubhouse 01/01/2050 4:00 7,500.00 17,674.2   01/01/2054 Clubhouse 01/01/2050 17,500.00 17,500.00 17,674.2   01/01/2054 Clubhouse 01/01/2024 0:00 \$2,100.00 \$52,080.1   Elicoring Title - Replace 01/01/2049 Clubhouse 01/01/2019 10:00 \$10,000.00 \$11,255.0   01/01/2039 Community 01/01/2039 10:00 10,000.00 15,125.9   01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9   01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0						138,006.39
01/01/2026 Clubhouse 01/01/2022 4:00 \$7,500.00 \$7,725.0   01/01/2030 Clubhouse 01/01/2036 4:00 7,500.00 8,694.5   01/01/2034 Clubhouse 01/01/2034 4:00 7,500.00 9,785.8   01/01/2038 Clubhouse 01/01/2038 4:00 7,500.00 11,014.0   01/01/2042 Clubhouse 01/01/2038 4:00 7,500.00 12,396.3   01/01/2046 Clubhouse 01/01/2044 4:00 7,500.00 13,952.2   01/01/2050 Clubhouse 01/01/2046 4:00 7,500.00 13,752.2   01/01/2054 Clubhouse 01/01/2050 4:00 7,500.00 17,674.2   01/01/2054 Clubhouse 01/01/2050 17,500.00 17,500.00 17,674.2   01/01/2054 Clubhouse 01/01/2024 0:00 \$2,100.00 \$52,080.1   Elicoring Title - Replace 01/01/2049 Clubhouse 01/01/2019 10:00 \$10,000.00 \$11,255.0   01/01/2039 Community 01/01/2039 10:00 10,000.00 15,125.9   01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9   01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0						
01/01/2030 Clubhouse 01/01/2026 4:00 7,500.00 8,694.5 01/01/2034 Clubhouse 01/01/2030 4:00 7,500.00 9,785.8 01/01/2038 Clubhouse 01/01/2034 4:00 7,500.00 11,014.0 01/01/2042 Clubhouse 01/01/2038 4:00 7,500.00 12,396.3 01/01/2046 Clubhouse 01/01/2042 4:00 7,500.00 13,952.2 01/01/2050 Clubhouse 01/01/2046 4:00 7,500.00 15,703.3 01/01/2054 Clubhouse 01/01/2050 4:00 7,500.00 15,703.3 01/01/2054 Clubhouse 01/01/2050 4:00 7,500.00 17,674.2 01/01/2054 Clubhouse 01/01/2050 4:00 7,500.00 52,080.1  Flooring LVT - Replace 01/01/2054 Clubhouse 01/01/2024 30:00 \$22,100.00 \$52,080.1  Flooring Tile - Replace 01/01/2043 Clubhouse 01/01/2013 30:00 \$20,000.00 \$34,048.6  Fountain - Refurbish 01/01/2029 Community 01/01/2019 10:00 \$10,000.00 \$11,255.0 01/01/2039 Community 01/01/2029 10:00 10,000.00 20,327.9 01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9 Furniture Chairs - Replace 01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0		Replace				
O1/01/2034   Clubhouse						\$ 7,725.00
01/01/2038   Clubhouse   01/01/2034   4:00   7,500.00   11,014.00						8,694.56
01/01/2042 Clubhouse 01/01/2038 4:00 7,500.00 12,396.3 01/01/2046 Clubhouse 01/01/2042 4:00 7,500.00 13,952.2 01/01/2050 Clubhouse 01/01/2046 4:00 7,500.00 15,703.3 01/01/2054 Clubhouse 01/01/2050 4:00 7,500.00 17,674.2 60,000.00 96,945.5 Flooring LVT - Replace 01/01/2054 Clubhouse 01/01/2024 30:00 \$22,100.00 \$52,080.1 20,100.00 \$52,080.1 Flooring Tile - Replace 01/01/2043 Clubhouse 01/01/2013 30:00 \$20,000.00 \$34,048.6 01/01/2043 Clubhouse 01/01/2013 30:00 \$20,000.00 \$34,048.6 Fountain - Refurbish 01/01/2029 Community 01/01/2019 10:00 \$10,000.00 \$11,255.0 01/01/2039 Community 01/01/2029 10:00 10,000.00 15,125.9 01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9 Furniture Chairs - Replace 01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0						9,785.80
01/01/2046 Clubhouse 01/01/2042 4:00 7,500.00 13,952.2 01/01/2050 Clubhouse 01/01/2046 4:00 7,500.00 15,703.3 01/01/2054 Clubhouse 01/01/2050 4:00 7,500.00 17,674.2 60,000.00 96,945.5  Flooring LVT - Replace 01/01/2054 Clubhouse 01/01/2024 30:00 \$22,100.00 \$52,080.1 22,100.00 52,080.1  Flooring Tile - Replace 01/01/2043 Clubhouse 01/01/2013 30:00 \$20,000.00 \$34,048.6  Fountain - Refurbish 01/01/2029 Community 01/01/2019 10:00 \$10,000.00 \$11,255.0 01/01/2039 Community 01/01/2029 10:00 10,000.00 15,125.9 01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9 01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9 Furniture Chairs - Replace 01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0				4:00		11,014.00
01/01/2050 Clubhouse 01/01/2046 4:00 7,500.00 15,703.3 01/01/2054 Clubhouse 01/01/2050 4:00 7,500.00 17,674.2 60,000.00 96,945.5   Flooring LVT - Replace 01/01/2054 Clubhouse 01/01/2024 30:00 \$22,100.00 \$52,080.1   Flooring Tile - Replace 01/01/2043 Clubhouse 01/01/2013 30:00 \$20,000.00 \$34,048.6   Fountain - Refurbish 01/01/2029 Community 01/01/2019 10:00 \$10,000.00 \$11,255.0 01/01/2039 Community 01/01/2029 10:00 10,000.00 15,125.9 01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9 01/01/2049 Community 01/01/2039 10:00 \$30,000.00 \$46,708.9   Furniture Chairs - Replace 01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0						12,396.36
01/01/2054 Clubhouse 01/01/2050 4:00 7,500.00 17,674.2 60,000.00 96,945.5  Flooring LVT - Replace 01/01/2054 Clubhouse 01/01/2024 30:00 \$22,100.00 \$52,080.1  Flooring Tile - Replace 01/01/2043 Clubhouse 01/01/2013 30:00 \$20,000.00 \$34,048.6  Fountain - Refurbish 01/01/2029 Community 01/01/2019 10:00 \$10,000.00 \$11,255.0 01/01/2039 Community 01/01/2029 10:00 10,000.00 15,125.9 01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9  Furniture Chairs - Replace 01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0	01/01/2046		01/01/2042	4:00		13,952.21
Flooring LVT - Replace  01/01/2054 Clubhouse 01/01/2024 30:00 \$22,100.00 \$52,080.1  22,100.00 \$52,080.1  Flooring Tile - Replace  01/01/2043 Clubhouse 01/01/2013 30:00 \$20,000.00 \$34,048.6  20,000.00 \$4,048.6  Fountain - Refurbish  01/01/2029 Community 01/01/2019 10:00 \$10,000.00 \$11,255.0  01/01/2039 Community 01/01/2029 10:00 10,000.00 15,125.9  01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9  Furniture Chairs - Replace  01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0						15,703.33
Flooring LVT - Replace  01/01/2054 Clubhouse 01/01/2024 30:00 \$22,100.00 \$52,080.1  22,100.00 52,080.1  Flooring Tile - Replace  01/01/2043 Clubhouse 01/01/2013 30:00 \$20,000.00 \$34,048.6  Fountain - Refurbish  01/01/2029 Community 01/01/2019 10:00 \$10,000.00 \$11,255.0  01/01/2039 Community 01/01/2029 10:00 10,000.00 15,125.9  01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9  Furniture Chairs - Replace  01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0	01/01/2054	Clubhouse	01/01/2050	4:00	7,500.00	17,674.24
01/01/2054 Clubhouse 01/01/2024 30:00 \$22,100.00 \$52,080.1  Flooring Tile - Replace 01/01/2043 Clubhouse 01/01/2013 30:00 \$20,000.00 \$34,048.6  20,000.00 \$10,000.00 \$11,255.0 01/01/2029 Community 01/01/2019 10:00 \$10,000.00 \$15,125.0 01/01/2039 Community 01/01/2029 10:00 10,000.00 15,125.9 01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9  Furniture Chairs - Replace 01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0					60,000.00	96,945.50
Flooring Tile - Replace 01/01/2043 Clubhouse 01/01/2013 30:00 \$20,000.00 \$34,048.6 20,000.00 \$4,048.6 20,000.00 \$11,255.0 01/01/2029 Community 01/01/2019 10:00 \$10,000.00 \$11,255.0 01/01/2039 Community 01/01/2029 10:00 10,000.00 15,125.9 01/01/2049 Community 01/01/2039 10:00 10,000.00 Furniture Chairs - Replace 01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0	Flooring LVT - Replace	ce				
Flooring Tile - Replace 01/01/2043 Clubhouse 01/01/2013 30:00 \$20,000.00 \$34,048.6 20,000.00 \$4,048.6 20,000.00 \$11,255.0 01/01/2029 Community 01/01/2019 10:00 \$10,000.00 \$11,255.0 01/01/2039 Community 01/01/2029 10:00 10,000.00 15,125.9 01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9 Furniture Chairs - Replace 01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0	01/01/2054	Clubhouse	01/01/2024	30:00	\$ 22,100.00	\$ 52,080.10
01/01/2043 Clubhouse 01/01/2013 30:00 \$20,000.00 \$34,048.6  20,000.00 \$34,048.6  Fountain - Refurbish  01/01/2029 Community 01/01/2019 10:00 \$10,000.00 \$11,255.0  01/01/2039 Community 01/01/2029 10:00 10,000.00 15,125.9  01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9  Furniture Chairs - Replace  01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0					22,100.00	52,080.10
01/01/2043 Clubhouse 01/01/2013 30:00 \$20,000.00 \$34,048.6  20,000.00 \$34,048.6  Fountain - Refurbish  01/01/2029 Community 01/01/2019 10:00 \$10,000.00 \$11,255.0  01/01/2039 Community 01/01/2029 10:00 10,000.00 15,125.9  01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9  Furniture Chairs - Replace  01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0						
Fountain - Refurbish  01/01/2029 Community 01/01/2019 10:00 \$10,000.00 \$11,255.0 01/01/2039 Community 01/01/2029 10:00 10,000.00 15,125.9 01/01/2049 Community 01/01/2039 10:00 10,000.00 20,327.9  Furniture Chairs - Replace 01/01/2044 Clubhouse 01/01/2019 25:00 \$2,000.00 \$3,507.0	,					
Fountain - Refurbish  01/01/2029	01/01/2043	Clubhouse	01/01/2013	30:00	\$ 20,000.00	\$ 34,048.66
01/01/2029         Community         01/01/2019         10:00         \$ 10,000.00         \$ 11,255.0           01/01/2039         Community         01/01/2029         10:00         10,000.00         15,125.9           01/01/2049         Community         01/01/2039         10:00         10,000.00         20,327.9           30,000.00         46,708.9           Furniture Chairs - Replace           01/01/2044         Clubhouse         01/01/2019         25:00         \$ 2,000.00         \$ 3,507.0					20,000.00	34,048.66
01/01/2039         Community         01/01/2029         10:00         10,000.00         15,125.9           01/01/2049         Community         01/01/2039         10:00         10,000.00         20,327.9           30,000.00         30,000.00         46,708.9           Furniture Chairs - Replace           01/01/2044         Clubhouse         01/01/2019         25:00         \$ 2,000.00         \$ 3,507.0	Fountain - Refurbish					
01/01/2039         Community         01/01/2029         10:00         10,000.00         15,125.9           01/01/2049         Community         01/01/2039         10:00         10,000.00         20,327.9           30,000.00         30,000.00         46,708.9           Furniture Chairs - Replace           01/01/2044         Clubhouse         01/01/2019         25:00         \$ 2,000.00         \$ 3,507.0	01/01/2029	Community	01/01/2019	10:00	\$ 10.000.00	\$ 11.255.09
01/01/2049     Community     01/01/2039     10:00     10,000.00     20,327.9       30,000.00     46,708.9       Furniture Chairs - Replace       01/01/2044     Clubhouse     01/01/2019     25:00     \$ 2,000.00     \$ 3,507.0		•				
30,000.00 46,708.9  Furniture Chairs - Replace 01/01/2044 Clubhouse 01/01/2019 25:00 \$ 2,000.00 \$ 3,507.0						20,327.94
Furniture Chairs - Replace 01/01/2044 Clubhouse 01/01/2019 25:00 \$ 2,000.00 \$ 3,507.0						46,708.93
01/01/2044 Clubhouse 01/01/2019 25:00 \$ 2,000.00 \$ 3,507.0	Furniture Chaire Do	nlace				
			01/01/0010	25.00	<b># 2 000 00</b>	# O FO7 O4
PRN:06/28/2025 See Preparer's Report		Clubhouse			\$ 2,000.00	\$ 3,507.01

See Disclosures and Summary of Significant Assumptions

Page 45 of 104



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

### Expenditure - By Component

		Service	Estimated		
Date	Location	Date	Life	Current Cost	Expenditure
Furniture Poker Tab	ole - Replace				
				2,000.00	3,507.01
01/01/2035	Clubhouse	01/01/2015	20:00	\$ 2,500.00	\$ 3,359.79
				2,500.00	3,359.79
Furniture Tables - R	•				
01/01/2048	Clubhouse	01/01/2023	25:00	\$ 2,500.00	\$ 4,933.97
				2,500.00	4,933.97
Gate Metal - Replac	-Δ				
01/01/2043	Pool	01/01/2013	30:00	\$ 1,000.00	¢ 1 702 42
01/01/2043	P00I	01/01/2013	30:00		\$ 1,702.43
				1,000.00	1,702.43
Gazebo - Refurbish					
01/01/2029	Community	01/01/2024	5:00	\$ 4,250.00	\$ 4,783.41
01/01/2034	Community	01/01/2029	5:00	4,250.00	5,545.29
01/01/2039	Community	01/01/2034	5:00	4,250.00	6,428.51
01/01/2044	Community	01/01/2039	5:00	4,250.00	7,452.40
01/01/2049	Community	01/01/2044	5:00	4,250.00	8,639.37
01/01/2054	Community	01/01/2049	5:00	4,250.00	10,015.40
				25,500.00	42,864.38
HVAC 3-Ton - Repla					
01/01/2035	Clubhouse	01/01/2020	15:00	\$ 5,000.00	\$ 6,719.58
01/01/2050	Clubhouse	01/01/2035	15:00	5,000.00	10,468.89
				10,000.00	17,188.47
HVAC 4-Ton - Repla	re				
01/01/2026	Clubhouse	01/01/2011	15:00	\$ 6,500.00	\$ 6,695.00
01/01/2027	Clubhouse	01/01/2012	15:00	6,500.00	6,895.85
01/01/2039	Clubhouse	01/01/2024	15:00	6,500.00	9,831.83
01/01/2041	Clubhouse	01/01/2026	15:00	6,500.00	10,430.59
01/01/2042	Clubhouse	01/01/2027	15:00	6,500.00	10,743.51
01/01/2054	Clubhouse	01/01/2039	15:00	6,500.00	15,317.68
23,23,252		2.7.2.7.200		39,000.00	59,914.46
				37,000.00	37,711.10
HVAC 5-Ton - Repla	ce				
01/01/2027	Clubhouse	01/01/2012	15:00	\$ 9,000.00	\$ 9,548.10
01/01/2027	Clubhouse	01/01/2012	15:00	9,000.00	9,548.10
01/01/2042	Clubhouse	01/01/2027	15:00	9,000.00	14,875.63

PRN:06/28/2025

See Preparer's Report

See Disclosures and Summary of Significant Assumptions

Page 46 of 104



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

### Expenditure - By Component

		Service	Estimated	0 10 1	E 19
Date	Location	Date	Life	Current Cost	Expenditure
HVAC 5-Ton - Replac	ee				
01/01/2042	Clubhouse	01/01/2027	15:00	\$ 9,000.00	\$ 14,875.63
				36,000.00	48,847.46
Irrigation System - R					
01/01/2035	Community	01/01/2015	20:00	\$ 5,000.00	\$ 6,719.58
				5,000.00	6,719.58
Lake - Dredge & Sho	reline Remediation				
01/01/2040	Community	01/01/1990	50:00	\$ 5,000.00	\$ 7,789.84
				5,000.00	7,789.84
				5,555.55	.,
Lake Controller - Rep	olace				
01/01/2030	Community	01/01/2015	15:00	\$ 5,000.00	\$ 5,796.37
01/01/2045	Community	01/01/2030	15:00	5,000.00	9,030.56
				10,000.00	14,826.93
Lighting - Replace					
01/01/2030	Community	01/01/2020	10:00	\$ 5,000.00	\$ 5,796.37
01/01/2030	Community	01/01/2030	10:00	5,000.00	7,789.84
01/01/2050	Community	01/01/2040	10:00	5,000.00	10,468.89
01/01/2000	community	01/01/2010		15,000.00	24,055.10
				13,000.00	24,033.10
Paver - Repair & Res	eal				
01/01/2026	Pool	01/01/2021	5:00	\$ 10,767.50	\$ 11,090.53
01/01/2028	Clubhouse	01/01/2023	5:00	9,735.00	10,637.70
01/01/2031	Pool	01/01/2026	5:00	10,767.50	12,856.96
01/01/2033	Clubhouse	01/01/2028	5:00	9,735.00	12,332.01
01/01/2036	Pool	01/01/2031	5:00	10,767.50	14,904.74
01/01/2038	Clubhouse	01/01/2033	5:00	9,735.00	14,296.18
01/01/2041	Pool	01/01/2036	5:00	10,767.50	17,278.68
01/01/2043	Clubhouse	01/01/2038	5:00	9,735.00	16,573.19
01/01/2046	Pool	01/01/2041	5:00	10,767.50	20,030.72
01/01/2048	Clubhouse	01/01/2043	5:00	9,735.00	19,212.86
01/01/2051	Pool	01/01/2046	5:00	10,767.50	23,221.10
01/01/2053	Clubhouse	01/01/2048	5:00	9,735.00	22,272.98
				123,015.00	194,707.65
Pool - Resurface					
01/01/2025	Pool	01/01/2010	15:00	\$ 43,000.00	\$ 43,000.00
01/01/2040	Pool	01/01/2025	15:00	43,000.00	66,992.60

PRN:06/28/2025

See Preparer's Report

See Disclosures and Summary of Significant Assumptions

Page 47 of 104



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

### Expenditure - By Component

Date	Location	Service Date	Estimated Life	Current Cost	Expenditure
Pool Chlorination - F	Replace				
, , , , , , , , , , , , , , , , , , , ,			_	86,000.00	109,992.60
01/01/2031	Pool	01/01/2021	10:00	\$ 3,500.00	\$ 4,179.18
01/01/2041	Pool	01/01/2031	10:00	3,500.00	5,616.47
01/01/2051	Pool	01/01/2041	10:00	3,500.00	7,548.07
				10,500.00	17,343.72
Pool Filter - Replace					
01/01/2027	Pool	01/01/2012	15:00	\$ 1,750.00	\$ 1,856.58
01/01/2027	Pool	01/01/2012	15:00	1,750.00	1,856.58
01/01/2042	Pool	01/01/2027	15:00	1,750.00	2,892.48
01/01/2042	Pool	01/01/2027	15:00	1,750.00	2,892.48
				7,000.00	9,498.12
Pool Furniture - Rep	lace				
01/01/2029	Pool	01/01/2019	10:00	\$ 12,000.00	\$ 13,506.11
01/01/2039	Pool	01/01/2029	10:00	12,000.00	18,151.08
01/01/2049	Pool	01/01/2039	10:00	12,000.00	24,393.53
			_	36,000.00	56,050.72
Pool Heater - Replac	` <del>^</del>				
01/01/2025	Pool	01/01/2018	7:00	\$ 8,500.00	\$ 8,500.00
01/01/2030	Pool	01/01/2018	12:00	8,500.00	9,853.83
01/01/2030	Pool	01/01/2018	12:00	8,500.00	9,853.83
01/01/2030	Pool	01/01/2018	12:00	8,500.00	9,853.83
01/01/2032	Pool	01/01/2025	7:00	8,500.00	10,453.93
01/01/2039	Pool	01/01/2032	7:00	8,500.00	12,857.01
01/01/2042	Pool	01/01/2030	12:00	8,500.00	14,049.20
01/01/2042	Pool	01/01/2030	12:00	8,500.00	14,049.20
01/01/2042	Pool	01/01/2030	12:00	8,500.00	14,049.20
01/01/2046	Pool	01/01/2039	7:00	8,500.00	15,812.50
01/01/2053	Pool	01/01/2046	7:00	8,500.00	19,447.39
01/01/2054	Pool	01/01/2042	12:00	8,500.00	20,030.81
01/01/2054	Pool	01/01/2042	12:00	8,500.00	20,030.81
01/01/2054	Pool	01/01/2042	12:00	8,500.00	20,030.81
				119,000.00	198,872.35
Pool Sauna - Refurb	ish				
01/01/2030	Clubhouse	01/01/2020	10:00	\$ 2,500.00	\$ 2,898.19
01/01/2040	Clubhouse	01/01/2030	10:00	2,500.00	3,894.92

PRN:06/28/2025

See Preparer's Report

See Disclosures and Summary of Significant Assumptions

Page 48 of 104



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

### Expenditure - By Component

		Service	Estimated		
Date	Location	Date	Life	Current Cost	Expenditure
Pool Sauna - Refurbi	sh				
01/01/2050	Clubhouse	01/01/2040	10:00	\$ 2,500.00	\$ 5,234.44
01/01/2030	Clubillouse	01/01/2040	10.00	7,500.00	12,027.55
				7,300.00	12,027.33
Remodel Auditorium	n - Remodel				
01/01/2030	Clubhouse	01/01/2020	10:00	\$ 10,000.00	\$ 11,592.74
01/01/2033	Clubhouse	01/01/2023	10:00	5,000.00	6,333.85
01/01/2040	Clubhouse	01/01/2030	10:00	10,000.00	15,579.67
01/01/2043	Clubhouse	01/01/2033	10:00	5,000.00	8,512.17
01/01/2050	Clubhouse	01/01/2040	10:00	10,000.00	20,937.78
01/01/2053	Clubhouse	01/01/2043	10:00	5,000.00	11,439.64
				45,000.00	74,395.85
Remodel Billiard Rm	Domesial				
		01/01/2020			+
	01/01/2030 Clubhouse		10:00	\$ 2,000.00	\$ 2,318.55
01/01/2040	Clubhouse	01/01/2030	10:00	2,000.00	3,115.93
01/01/2050	Clubhouse	01/01/2040	10:00	2,000.00	4,187.56
				6,000.00	9,622.04
Remodel Clubhouse	Restrooms - Remodel				
01/01/2038	Clubhouse	01/01/2013	25:00	\$ 40,000.00	\$ 58,741.35
			<del></del>	40,000.00	58,741.35
				10,000.00	33,7.1133
Remodel Kitchen - R	emodel				
01/01/2026	Clubhouse	01/01/2016	10:00	\$ 5,000.00	\$ 5,150.00
01/01/2036	Clubhouse	01/01/2026	10:00	5,000.00	6,921.17
01/01/2046	Clubhouse	01/01/2036 10:00		5,000.00	9,301.47
				15,000.00	21,372.64
Domondol Montina Dr	n Domondol				
Remodel Meeting Rr		24/24/2247			
01/01/2027	Clubhouse	01/01/2017	10:00	\$ 18,700.00	\$ 19,838.83
01/01/2037	Clubhouse	01/01/2027	10:00	18,700.00	26,661.73
01/01/2047	Clubhouse	01/01/2037	10:00	18,700.00	35,831.13
				56,100.00	82,331.69
Security System - Re	place				
01/01/2025	Community	01/01/2010	15:00	\$ 21,000.00	\$ 21,000.00
01/01/2040	Community	01/01/2025	15:00	21,000.00	32,717.32
01/01/2040	Community	31/01/2023	13.00	42,000.00	53,717.32
				42,000.00	33,111.32
Sewer Line - Repairs					
01/01/2026	Community	01/01/2021	5:00	\$ 150,000.00	\$ 154,500.00
DBN:06/29/2025			arar's Danart		

PRN:06/28/2025

See Preparer's Report

See Disclosures and Summary of Significant Assumptions

Page 49 of 104



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

### Expenditure - By Component

		Service	Estimated		
Date	Location	Date	Life	Current Cost	Expenditur
wer Line - Repairs					
01/01/2031	Community	01/01/2026	5:00	\$ 150,000.00	\$ 179,107.8
01/01/2036	Community	01/01/2031	5:00	150,000.00	207,635.0
01/01/2041	Community	01/01/2036	5:00	150,000.00	240,705.9
01/01/2046	Community	01/01/2041	5:00	150,000.00	279,044.1
01/01/2051	Community	01/01/2046	5:00	150,000.00	323,488.6
				900,000.00	1,384,481.7
uffleboard - Resur	face				
01/01/2027	Clubhouse	01/01/2015	12:00	\$ 5,000.00	\$ 5,304.5
01/01/2034	Clubhouse	01/01/2022	12:00	5,000.00	6,523.8
01/01/2039	Clubhouse	01/01/2027	12:00	5,000.00	7,562.9
01/01/2046	Clubhouse	01/01/2034	12:00	5,000.00	9,301.4
01/01/2051	Clubhouse	01/01/2039	12:00	5,000.00	10,782.9
				25,000.00	39,475.
uffleboard Benche	es Wood - Repair & Rep	blace			
01/01/2026	Clubhouse	01/01/2021	5:00	\$ 2,500.00	\$ 2,575.0
01/01/2031	Clubhouse	01/01/2026	5:00	2,500.00	2,985.
01/01/2036	Clubhouse	01/01/2031	5:00	2,500.00	3,460.5
01/01/2041	Clubhouse	01/01/2036	5:00	2,500.00	4,011.
01/01/2046	Clubhouse	01/01/2041	5:00	2,500.00	4,650.7
01/01/2051	Clubhouse	01/01/2046	5:00	2,500.00	5,391.4
				15,000.00	23,074.
uffleboard Shade	Structures - Refurbish				
01/01/2025	Clubhouse	01/01/1990	35:00	\$ 11,875.00	\$ 11,875.0
01/01/2028	Clubhouse	01/01/1991	37:00	11,875.00	12,976.
0170172020	old bill das	01/01/17/1		23,750.00	24,851.
gnage Monument	Pofurbish			22,7 23.23	,,
01/01/2038		01/01/2022	15.00	\$ 12,500.00	¢ 10 2E4
	Community	01/01/2023	15:00		\$ 18,356.6
01/01/2053	Community	01/01/2038	15:00	12,500.00	28,599.
				25,000.00	46,955.7
nage Streets/Mis	c - Repair & Replace				
	Community	01/01/2020	10:00	\$ 8,000.00	\$ 9,274.
01/01/2030	•			8,000.00	12,463.
01/01/2030 01/01/2040	Community	01/01/2030	10:00	0,000.00	12,100.
	Community Community	01/01/2030 01/01/2040	10:00	8,000.00	16,750.2

PRN:06/28/2025

Storm Water Drainage - Repairs



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

### Expenditure - By Component

		Service	Estimated		
Date	Location	Date	Life	Current Cost	Expenditure
Storm Water Draina	ge - Repairs				
01/01/2030	Community	01/01/2025	5:00	\$ 10,000.00	\$ 11,592.74
01/01/2035	Community	01/01/2030	5:00	10,000.00	13,439.16
01/01/2040	Community	01/01/2035	5:00	10,000.00	15,579.67
01/01/2045	Community	01/01/2040	5:00	10,000.00	18,061.11
01/01/2050	Community	01/01/2045	5:00	10,000.00	20,937.78
			·	50,000.00	79,610.46
Wall Block - Repair					
01/01/2025	Community	01/01/2020	5:00	\$ 14,625.00	\$ 14,625.00
01/01/2030	Community	01/01/2025	5:00	14,625.00	16,954.38
01/01/2035	Community	01/01/2030	5:00	14,625.00	19,654.78
01/01/2040	Community	01/01/2035	5:00	14,625.00	22,785.27
01/01/2045	Community	01/01/2040	5:00	14,625.00	26,414.38
01/01/2050	Community	01/01/2045	5:00	14,625.00	30,621.50
				87,750.00	131,055.31
W"   D					
Windows - Partial Re	•				
01/01/2030	Clubhouse	01/01/2020	10:00	\$ 2,500.00	\$ 2,898.19
01/01/2040	Clubhouse	01/01/2030	10:00	2,500.00	3,894.92
01/01/2050	Clubhouse	01/01/2040	10:00	2,500.00	5,234.44
				7,500.00	12,027.55
Windscreen - Replac	.0				
·		04 /04 /0045	10.00	<b>*</b> 0 500 00	<b>*</b> 0 <b>5</b> 0 0 0 0
01/01/2025	Clubhouse	01/01/2015	10:00	\$ 2,500.00	\$ 2,500.00
01/01/2035	Clubhouse	01/01/2025	10:00	2,500.00	3,359.79
01/01/2045	Clubhouse	01/01/2035	10:00	2,500.00	4,515.28
				7,500.00	10,375.07



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

Item Number		1 Common Area			Measi	urement Bas	Sq Yds		
Туре					Estima		20 Years		
Category			Pavement			Cost		\$ 12.00	
Tracking			Logisti	cal					
Method			Fix	ed					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Community		Good	01/01/2011	01/01/2031	6:00	20:00	17,500	210,000.00	250,750.98
								210,000.00	250,750.98
Comments									





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Component List - Full Detail

Comments

Item Number	<del>-</del>			2	Measurement Basis				Sq Yds	
Туре				rea	Estima		5 Years			
Category		Pavement			Basis Cost					
Tracking Logistical			cal							
Method	Fixed									
			Service	Replace	Rem	Adj		Current	Future	
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost	
Community	Streets	Good	01/01/2021	01/01/2026	1:00	5:00	15,000	15,000.00	15,450.00	
Community	Parking Lot	Good	01/01/2024	01/01/2029	4:00	5:00	2,500	2,500.00	2,813.77	
								17,500.00	18,263.77	





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Component List - Full Detail

Item Number				3	Measurement Basis			Allow	
Туре			Common Area		Estima	ated Useful L	ife		15 Years
Category		Equipment			Basis (	Cost		\$ 20,000.00	
Tracking			Logisti	cal					
Method		Fixed							
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse		Good	01/01/2011	01/01/2026	1:00	15:00	1	20,000.00	20,600.00
							_	20,000.00	20,600.00
Comments									



Televisions, Sound equipment,



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Component List - Full Detail

#### Billiard Table - Refurbish

Item Number		4 Common Area			Measurement Basis				Each	
Туре					Estima	ited Useful I		5 Years		
Category		Furniture			Basis Cost				\$ 1,000.00	
Tracking			Logisti	cal						
Method			Fix	ed						
			Service	Replace	Rem	Adj		Current	Future	
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost	
Clubhouse	Billiards	Good	01/01/2024	01/01/2029	4:00	5:00	3	3,000.00	3,376.53	
								3,000.00	3,376.53	
Comments										





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Component List - Full Detail

Item Number		5			Measi	urement Bas	Job			
Туре	「ype Comr		Common Ar	rea	Estimated Useful Life				10 Years	
Category		Painting			Basis (	Cost			\$ 24,000.00	
Tracking	g Logistical									
Method		Fixed								
			Service	Replace	Rem	Adj		Current	Future	
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost	
Clubhouse		Good	01/01/2016	01/01/2026	1:00	10:00	1	24,000.00	24,720.00	
							_	24,000.00	24,720.00	
0										

#### Comments





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Component List - Full Detail

Bldg Exterior Gutters - Replace

Item Number				6	Measu	urement Bas	is		Allow
Туре			Common Ar	ea	Estima	ated Useful L	ife		12 Years
Category			Ro	oof	Basis (	Cost			\$ 2,000.00
Tracking			Logisti	cal					
Method			Fix	ed					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse		Good	01/01/2019	01/01/2031	6:00	12:00	1	2,000.00	2,388.10
								2,000.00	2,388.10
Comments									





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Component List - Full Detail

Item Number		7			Measurement Basis				Squares
Туре	Common Area		rea	Estima		25 Years			
Category			Ro	oof	Basis	Cost			\$ 600.00
Tracking			Logisti	cal					
Method			Fix	ed					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse		Good	01/01/2020	01/01/2045	20:00	25:00	140	84,000.00	151,713.34
							_	84,000.00	151,713.34
Comments									



2020 - \$121,000



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

Concrete -	Dartial	Don	laco
Concrete -	raillai	Kepi	lace

Item Number				8	Measu	irement Bas	sis		Allow
Туре			Common Area		Estima	ited Useful I	_ife		2 Years
Category			Paveme	ent	Basis (	Cost			\$ 12,000.00
Tracking			Logisti	cal					
Method			Fix	red					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Community		Good	01/01/2024	01/01/2026	1:00	2:00	1	12,000.00	12,360.00
							_	12,000.00	12,360.00
Comments									





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Component List - Full Detail

Defibril	lators -	Ren	lace
	iatui 3 -	IVED	Iacc

Item Number			9	Measu	urement Bas	is		Each
Туре		Common Ar	ea	Estima	ated Useful L	ife		12 Years
Category		Safety/Secur	ity	Basis (	Cost			\$ 2,000.00
Tracking		Logisti	cal					
Method		Fix	ed					
		Service	Replace	Rem	Adj		Current	Future
Location Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse	Good	01/01/2017	01/01/2029	4:00	12:00	1	2,000.00	2,251.02
							2,000.00	2,251.02

#### Comments





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

Doors - Partial Replace
-------------------------

Item Number				10	Measu	urement Bas	is		Allow
Туре			Common Ar	rea	Estima	ated Useful L	ife		10 Years
Category			Windows, Doo	ors	Basis (	Cost			\$ 2,500.00
Tracking			Logisti	cal					
Method			Fix	red					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse		Good	01/01/2020	01/01/2030	5:00	10:00	1	2,500.00	2,898.19
								2,500.00	2,898.19
Comments									





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

Item Number				11	Measu	ırement Bas	is		Job
Туре			Common Ar	ea	Estima	ated Useful L	ife		15 Years
Category			Safety/Secur	ity	Basis (	Cost			\$ 22,000.00
Tracking			Logisti	cal					
Method			Fix	ed					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse		Good	01/01/2010	01/01/2025	0:00	15:00	1	22,000.00	22,000.00
								22,000.00	22,000.00
Comments									





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

Exhaust	Fan	- Rer	olace

Item Number	em Number 1		12	2 Measurement Basis			Job		
Type Category Tracking			Common Ar	ea	Estimated Useful Life				35 Years
			Pool		Basis Cost				\$ 2,000.00
			Logisti	cal					
Method			Fix	ed					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Pool		Good	01/01/2005	01/01/2040	15:00	35:00	1	2,000.00	3,115.93
								2,000.00	3,115.93
Comments									





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Component List - Full Detail

Fence Metal - F	Replace
-----------------	---------

LF		İS	Measurement Basis				13		Item Number	
40 Years		ife	Estimated Useful Life				Common Area		Туре	
\$ 80.00			Cost	Basis C	ce			Category		
					cal			Tracking		
					ed	Fixed			Method	
Future	Current		Adj	Rem	Replace	Service				
Cost	Cost	Quantity	Life	Life	Date	Date	Condition	Desc.	Location	
10,578.22	6,400.00	80	40:00	17:00	01/01/2042	01/01/2002	Good	Perimeter	Community	
10,578.22	6,400.00									

#### Comments





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Component List - Full Detail

Fence	Vinv	l - Re	place
	viiiy	1 110	piacc

Item Number	tem Number			14 Measurement Basis			is	LF	
Type Category Tracking			Common Ar	rea					25 Years
		,	Walls, Gates, Fer	nce				\$ 93.0	
			cal						
Method			Fix	red					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Community		Good	01/01/2024	01/01/2049	24:00	25:00	730	67,890.00	138,006.39
								67,890.00	138,006.39
Comments									



2024 - \$65,000



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Component List - Full Detail

T:1	F!	Danlass
Fitness	Equipment	<ul> <li>Replace</li> </ul>

Item Number	em Number		15	Measurement Basis				Allow	
Type Category Tracking			Common Ar	ea	Estimated Useful Life				4 Years
			Fitne	ess	Basis (	Cost		\$ 7,500.00	
			cal						
Method			Fix	ed					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse		Good	01/01/2022	01/01/2026	1:00	4:00	1	7,500.00	7,725.00
								7,500.00	7,725.00
Comments									



Funding Fitness equipment as an allowance to update every 4 years. Replace as needed.

- 2 Treadmills
- 1 Recumbent Bike
- 1 Upright Bike
- 1 Scale
- 1 Universal weight machine
- 2 Elliptical **Nordic** Track



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Component List - Full Detail

F	looring	IVT -	Repl	ace

Item Number	em Number 10		16	Measu	ırement Bas	is	Job		
Type Category Tracking			Common Ar	rea					30 Years
			Floor	ng					\$ 22,100.00
			cal						
Method			Fix	ed					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse		Good	01/01/2024	01/01/2054	29:00	30:00	1	22,100.00	52,080.10
								22,100.00	52,080.10
Comments									



2023 - LVT Flooring in the clubhouse was installed in 6/2023 cost 22,000



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Component List - Full Detail

Job		S	Measurement Basis				em Number 17		Item Number	
30 Years		Estimated Useful Life				pe Common Area		Туре		
\$ 20,000.00			Cost	Basis C	egory Flooring		Category			
					cal	Tracking Logistical				
					ed	Fixe			Method	
Future	Current		Adj	Rem	Replace	Service				
Cost	Cost	Quantity	Life	Life	Date	Date	Condition	Desc.	Location	
34,048.66	20,000.00	1	30:00	18:00	01/01/2043	01/01/2013	Good	Meeting Rm	Clubhouse	
34,048.66	20,000.00									

#### Comments





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

Fountai	n D	fur	hich
Fountai	H - K	arur	OISH

Item Number				18	Measurement Basis				Allow	
Туре		Common Ar	rea	Estimated Useful Life				10 Years		
Category			Equipme	Equipment		Cost			\$ 10,000.00	
Tracking			Logisti	cal						
Method			Fix	ed						
			Service	Replace	Rem	Adj		Current	Future	
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost	
Community		Good	01/01/2019	01/01/2029	4:00	10:00	1	10,000.00	11,255.09	
							_	10,000.00	11,255.09	
Comments										





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

Furnitura	Chaire	Dan	1000
Furniture	chairs -	Kep	lace

Item Number				19	Measurement Basis				Allow
Туре		Common Ar	rea	Estimated Useful Life				25 Years	
Category Furni			Furnitu	ıre	e Basis Cost				\$ 2,000.00
Tracking			Logisti	cal					
Method			Fix	red					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse	Auditorium	Good	01/01/2019	01/01/2044	19:00	25:00	1	2,000.00	3,507.01
								2,000.00	3,507.01
Comments									





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

### Component List - Full Detail

Item Number				20	Measurement Basis				Allow
Туре			Common Area		Estima	ated Useful L		20 Years \$ 2,500.00	
Category Tracking			Furniture		Basis (	Cost			
			Logisti	cal					
Method			Fix	red					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse	Billiards	Good	01/01/2015	01/01/2035	10:00	20:00	1	2,500.00	3,359.79
								2,500.00	3,359.79
Comments									





Page 71 of 104

Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

#### Component List - Full Detail

_				
Furn	itur△	Tables -	Reni	ace
ıuıı	ILUIC	Tables -	$11 \cup 11$	acc

Item Number				21	Measurement Basis				Allow
Туре		Common Area Furniture		Estima		25 Years			
Category Tracking				Basis (	Cost		\$ 2,500.00		
			Logisti	ical					
Method	Fixed								
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse	Auditorium	Good	01/01/2023	01/01/2048	23:00	25:00	1	2,500.00	4,933.97
								2,500.00	4,933.97
Comments									



2023 - Tables for the clubhouse bought in 2023 cost 2,300.00



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Gate	Metal	- Ren	lace
Juic	IVICTUI	I C D	uoc

Item Number	em Number 22			Measu	ırement Bas	is	Each		
Туре		Common Area			ited Useful L	ife		30 Years	
Category	Walls, Gates, Fence Basis Cost				nce Basis Cost			\$ 500.00	
Tracking Logistical									
Method									
		Service	Replace	Rem	Adj		Current	Future	
Location Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost	
Pool	Good	01/01/2013	01/01/2043	18:00	30:00	2	1,000.00	1,702.43	
							1,000.00	1,702.43	

### Comments





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Gazebo -	

Allow		is	Measurement Basis						Item Number	
5 Years		ife	ted Useful L	Estima	ea	Common Area			Туре	
\$ 4,250.00			ost	Basis C	re	Furnitu			Category	
		Logistical						Tracking		
		Fixed							Method	
Future	Current		Adj	Rem	Replace	Service				
Cost	Cost	Quantity	Life	Life	Date	Date	Condition	Desc.	Location	
4,783.41	4,250.00	1	5:00	4:00	01/01/2029	01/01/2024	Good		Community	
4,783.41	4,250.00									

# Comments



2024 - Gazebo repair: deck and ramp, 2024 cost 4170.35



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

HVAC 3-Ton - Replace

Each		S	Measurement Basis			24			Item Number	
15 Years		ife	ted Useful Li	Estima	ea	Common Ar			Туре	
\$ 5,000.00			Cost	Basis (	AC O	HVA			Category	
		Logistical							Tracking	
		Fixed							Method	
Future	Current		Adj	Rem	Replace	Service				
Cost	Cost	Quantity	Life	Life	Date	Date	Condition	Desc.	Location	
6,719.58	5,000.00	1	15:00	10:00	01/01/2035	01/01/2020	Good	G028112	Clubhouse	
6,719.58	5,000.00									

### Comments



Daikin. Model# 4MXS36RMVJU



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Н١	/AC	4-7	Γnn	- R	en.	lace
	$I \cap I$	т-	uui	- 11	$\sim$	ucc

Item Number	25	Measurement Basis	Each
Туре	Common Area	Estimated Useful Life	15 Years
Category	HVAC	Basis Cost	\$ 6,500.00
Tracking	Logistical		
Method	Fixed		

			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse	ICP-E1046	0144 Good	01/01/2011	01/01/2026	1:00	15:00	1	6,500.00	6,695.00
Clubhouse	D - 240107	7273 Good	01/01/2024	01/01/2039	14:00	15:00	1	6,500.00	9,831.83
Clubhouse	ICP-E1129	1491 Good	01/01/2012	01/01/2027	2:00	15:00	1	6,500.00	6,895.85
								19,500.00	23,422.68

### Comments



Daikin Model# GSXN404810AB

International Comfort Products, Model# NXA648GKA100



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

### HVAC 5-Ton - Replace

Item Number	•			26	Measu	ırement Bas	is	Each		
Туре			Common Ar	·ea	Estima	ated Useful L	15 Years			
Category		HVAC			HVAC Basis Cost	Basis Cost				\$ 9,000.00
Tracking			Logisti	cal						
Method			Fix	red						
			Service	Replace	Rem	Adj		Current	Future	
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost	
Clubhouse	E113801932	Good	01/01/2012	01/01/2027	2:00	15:00	1	9,000.00	9,548.10	
Clubhouse	E113906476	Good	01/01/2012	01/01/2027	2:00	15:00	1	9,000.00	9,548.10	

### Comments



International Comfort Products, Model# NXA660GKA100



19,096.20

18,000.00

Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

Item Number				27	Measu	ırement Bas	is	Allow		
Туре		Common Area			Estimated Useful Life				20 Years	
Category			Irrigati	Basis (	Cost		\$ 5,000.00			
Tracking			Logisti	Logistical						
Method			Fix	ed						
			Service	Replace	Rem	Adj		Current	Future	
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost	
Community		Good	01/01/2015	01/01/2035	10:00	20:00	1	5,000.00	6,719.58	
								5,000.00	6,719.58	
Comments										





Analysis Date - January 1, 2025

Inflation: 3.00% Investment: 2.00% Contribution Factor: 0.00% Calc: Future

### Component List - Full Detail

Lake - Dredge & Shoreline Remediation

Item Number				28	Measu	urement Bas	is		Allow
Туре	Common Area			ea	Estima	ated Useful L	ife	50 Yea	
Category		Lakes			Basis Cost				\$ 5,000.00
Tracking	king Logistical								
Method			Fix						
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Community		Good	01/01/1990	01/01/2040	15:00	50:00	1	5,000.00	7,789.84
								5,000.00	7,789.84
Comments									



Condition long term - state of the lakes - Lake Doctors. Per Lake Doctors the state of the lake is very

good.



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

Lake Controller - Replace
---------------------------

Item Number 29			29	Measurement Basis			Job			
Туре		Common Area		rea	Estimated Useful Life				15 Years	
Category			Lak	ces	Basis (	Cost			\$ 5,000.00	
Tracking			Logisti	cal						
Method			Fix	ed						
			Service	Replace	Rem	Adj		Current	Future	
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost	
Community		Good	01/01/2015	01/01/2030	5:00	15:00	1	5,000.00	5,796.37	
								5,000.00	5,796.37	
Comments										





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Item Number 30			30	Measurement Basis			Allow		
Туре			Common Ar	ea	Estima	ated Useful L	ife		10 Years
Category			Lighti	ng	Basis (	Cost			\$ 5,000.00
Tracking			Logisti	cal					
Method			Fix	ed					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Community		Good	01/01/2020	01/01/2030	5:00	10:00	1	5,000.00	5,796.37
								5,000.00	5,796.37
Comments									



Funding to replace wall mounted, pole, lighting as needed.



Analysis Date - January 1, 2025

Inflation: 3.00% Investment: 2.00% Contribution Factor: 0.00% Calc: Future

### Component List - Full Detail

Paver -	Repair	&	Reseal
---------	--------	---	--------

Item Number		31		Measurement Basis				Sq Ft	
Туре	Туре		Common Area		Estima	ated Useful L		5 Years	
Category		Pavement		Basis (	Basis Cost			\$ 2.95	
Tracking			Logisti	cal					
Method			Fix	ed					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Pool	Pool	Good	01/01/2021	01/01/2026	1:00	5:00	3,650	10,767.50	11,090.53
Clubhouse	Entry	Good	01/01/2023	01/01/2028	3:00	5:00	3,300	9,735.00	10,637.70
								20,502.50	21,728.23

### Comments



2023 - The front driveway was installed by Alpha in 3/10/23 at a cost of 31,500.00

2025 - Pool pavers cleaned and sealed by Pool Werks.



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Pool	-	Resurface
------	---	-----------

Tool Resulta	100								
Item Number			32	Measurement Basis			Job		
Туре			rea	Estima	ated Useful l		15 Years		
Category		Pool		ool	Basis (	Cost		\$ 43,000.00	
Tracking			cal						
Method			Fix	xed					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Pool		Good	01/01/2010	01/01/2025	0:00	15:00	1	43,000.00	43,000.00
								43,000.00	43,000.00

### Comments



2025 - Pool Werks



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Pool	Chlorination	- Replace
1 001	ornornia tion	i - Nopiaco

Item Number	tem Number 33			33	Measurement Basis			Job	
Туре	Type Comm		Common Ar	rea	Estimated Useful Life				10 Years
Category			Po	ool	Basis	Cost			\$ 3,500.00
Tracking			Logisti	cal					
Method			Fix	red					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Pool		Good	01/01/2021	01/01/2031	6:00	10:00	1	3,500.00	4,179.18
								3,500.00	4,179.18
Comments									

# SHAYWARD TO SHARE THE SHAR

Model# TPS-820



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Pool	Filter	- Rep	lace
1 001	1 11101	- INCO	lacc

Item Number	35	Measurement Basis	Each
Туре	Common Area	Estimated Useful Life	15 Years
Category	Pool	Basis Cost	\$ 1,750.00
Tracking	Logistical		
Method	Fixed		

			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Pool	2012 - 107	SB01 Good	01/01/2012	01/01/2027	2:00	15:00	1	1,750.00	1,856.58
Pool	2012 - 106	SI030 Good	01/01/2012	01/01/2027	2:00	15:00	1	1,750.00	1,856.58
								3,500.00	3,713.16

### Comments



Model# CJ250



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Pool	Furniture -	Ren	lace
1 001	i ui i ii tui c -	NCD	Iacc

Item Number			36	Measu	urement Bas	is	Allow			
Туре			rea	Estimated Useful Life				10 Years		
Category			ool	Basis Cost			\$ 12,000.00			
Tracking	racking Logistical			cal						
Method			Fix	red						
			Service	Replace	Rem	Adj		Current	Future	
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost	
Pool		Good	01/01/2019	01/01/2029	4:00	10:00	1 _	12,000.00	13,506.11	
								12,000.00	13,506.11	

### Comments



2019 - \$10,614 from FL Patio Furniture



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Pool	Heater	- Rei	place
FUUI	пеацы	- KG	piace

Item Number	37	Measurement Basis	Each
Туре	Common Area	Estimated Useful Life	12 Years
Category	Pool	Basis Cost	\$ 8,500.00
Tracking	Logistical		
Method	Adjusted		

			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Pool	181100379	Good	01/01/2018	01/01/2030	5:00	12:00	1	8,500.00	9,853.83
Pool	181101524	Good	01/01/2018	01/01/2025	0:00	7:00	1	8,500.00	8,500.00
Pool	181101520	Good	01/01/2018	01/01/2030	5:00	12:00	1	8,500.00	9,853.83
Pool	181100376	Good	01/01/2018	01/01/2030	5:00	12:00	1	8,500.00	9,853.83
							_	34,000.00	38,061.49

### Comments



Model# 166ARDSBPR



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

Item Number		38 Common Area			Measi	urement Bas		Allow	
Туре					Estima	ated Useful L		10 Years	
Category			ool	Basis (	Cost	\$ 2,500.00			
Tracking Logistical				cal					
Method			Fix	ed					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse		Good	01/01/2020	01/01/2030	5:00	10:00	1	2,500.00	2,898.19
								2,500.00	2,898.19
Comments									





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future


# Component List - Full Detail

Remodel	Auditorium	- Remodel

Item Number		39 Measurement Basis						Allow		
Туре			Common Ar	rea	Estima	ited Useful I	10 Years			
Category			Remo	del	Basis Cost			\$ 10,000.00		
Tracking			cal							
Method			Fix	red						
			Service	Replace	Rem	Adj		Current	Future	
Location	Desc	Condition	Date	Date	Life	Life	Ouantity	Cost	Cost	

			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse	Auditorium	Good	01/01/2020	01/01/2030	5:00	10:00	1	10,000.00	11,592.74
Clubhouse	Laundry Rm	Good	01/01/2023	01/01/2033	8:00	10:00	0.5	5,000.00	6,333.85
								15,000.00	17,926.59

### Comments



Remodel allowance to include Refrigerator replace (2022),



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

### Remodel Billiard Rm - Remodel

Item Number	er 40			40	Measurement Basis				Allow	
Туре	Common Area			rea	Estima	ated Useful L	10 Years			
Category		Remodel			Basis (	Cost	\$ 2,000.00			
Tracking		cal								
Method			Fix	red						
			Service	Replace	Rem	Adj		Current	Future	
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost	
Clubhouse	Billiards	Good	01/01/2020	01/01/2030	5:00	10:00	1	2,000.00	2,318.55	
								2,000.00	2,318.55	
Comments										





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

### Remodel Clubhouse Restrooms - Remodel

Allow		is	Measurement Basis						Item Number			
25 Years		Estimated Useful Life				Common Are			Туре			
\$ 40,000.00			ost	Basis (	lel	Remod		Category				
						Logistic			Tracking			
				Method								
urrent Future	Curi		Adj	Rem	Replace	Service						
Cost Cost	(	Quantity	Life	Life	Date	Date	Condition	Desc.	Location			
000.00 58,741.35	40,00	1	25:00	13:00	01/01/2038	01/01/2013	Good		Clubhouse			
000.00 58,741.35	40,00	_										

### Comments





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

Item Number				42	Measi	ırement Bas	is		Allow
Туре	pe Common Area			ea	Estimated Useful Life				10 Years
Category			Remo	del	Basis Cost				\$ 5,000.00
Tracking Logistical									
Method									
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse	Kitchen	Good	01/01/2016	01/01/2026	1:00	10:00	1	5,000.00	5,150.00
								5,000.00	5,150.00
Comments									





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Allow		İs	Measurement Basis Estimated Useful Life						Item Number	
10 Years		ife					Common Area			
\$ 18,700.00	\$ 18,70	Remodel Basis Cost				Remodel Basis Cost				Category
			ů						Tracking	
		Fixed							Method	
Future	Current		Adj	Rem	Replace	Service				
Cost	Cost	Quantity	Life	Life	Date	Date	Condition	Desc.	Location	
19,838.83	18,700.00	1	10:00	2:00	01/01/2027	01/01/2017	Good	Meeting Rm	Clubhouse	
19,838.83	18,700.00									

# Comments





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Security	ιSι	ıstem	- R	enla?	CE
Security	/ J y	Stelli	- 11	Cpia	しし

Item Number				45	Measurement Basis				Allow		
Туре			Common Area			nted Useful L	ife		15 Years		
Category		Safety/Security			Basis (	Cost			\$ 21,000.00		
Tracking			Logistical								
Method			Fix								
			Service	Replace	Rem	Adj		Current	Future		
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost		
Community		Good	01/01/2010	01/01/2025	0:00	15:00	1	21,000.00	21,000.00		
							_	21,000.00	21,000.00		
0											

### Comments



2013 -



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

C ~ ~ ~	1:00	Repairs
	I III ← -	RANAIIC

Item Number				46	Measu	irement Bas	is		Allow
Туре					Estima	ited Useful I		5 Years	
Category					Basis Cost				\$ 150,000.00
Tracking			Logisti	cal					
Method		Fixed							
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Community		Good	01/01/2021	01/01/2026	1:00	5:00	1	150,000.00	154,500.00
							_	150,000.00	154,500.00
Comments									



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

### Shuffleboard - Resurface

Comments

Item Number				47	Measurement Basis				Job
Туре			Common Ar	n Area Estimated Useful Life					12 Years
Category			Paveme	ent	Basis Cost				\$ 5,000.00
Tracking			Logisti	cal					
Method									
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse	50% - 2022	Good	01/01/2022	01/01/2034	9:00	12:00	1	5,000.00	6,523.87
Clubhouse	50% - 2027	Good	01/01/2015	01/01/2027	2:00	12:00	1	5,000.00	5,304.50
								10,000.00	11,828.37





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Shuffleboard Benches Wood - Repair & Replace

Item Number				48	Measu	irement Bas	is		Allow
Туре			Common Ar	rea	Estimated Useful Life				5 Years
Category	Furniture Basis Cost				Basis Cost				\$ 2,500.00
Tracking			Logisti	cal	ıl				
Method									
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse		Good	01/01/2021	01/01/2026	1:00	5:00	1	2,500.00	2,575.00
								2,500.00	2,575.00
Comments									



Funding to maintain the shuffleboard wood benches.



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

### Shuffleboard Shade Structures - Refurbish

Item Number	Measurement Basis						em Number		49			is		Sq Ft
Туре	Common Area				Estima	nted Useful L		35 Years						
Category		,	Walls, Gates, Fer	ice	Basis (	Cost			\$ 12.50					
Tracking	cal													
Method		Adjusted												
			Service	Replace	Rem	Adj		Current	Future					
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost					
Clubhouse	NORTH	Good	01/01/1991	01/01/2028	3:00	37:00	950	11,875.00	12,976.13					
Clubhouse	SOUTH	Good	01/01/1990	01/01/2025	0:00	35:00	950	11,875.00	11,875.00					
							_	23,750.00	24,851.13					





Comments

Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Signage Monument -	Refurbish
--------------------	-----------

Item Number	Item Number50TypeCommon AreaCategoryFurniture			50	Measurement Basis Estimated Useful Life			Allow		
Туре				rea					15 Years	
Category				ıre	Basis (	Cost		\$ 12,500.00		
Tracking Logistical				cal						
Method			Fix	red						
			Service	Replace	Rem	Adj		Current	Future	
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost	
Community		Good	01/01/2023	01/01/2038	13:00	15:00	1	12,500.00	18,356.67	
								12,500.00	18,356.67	
Comments										



2023 -



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Signage Streets/Misc - Repair & Replace

Item Number				51	Measurement Basis				Allow
Type		Common Area		Estima	ated Useful L	ife		10 Years	
Category Tracking			Furnitu	Furniture		Cost			\$ 8,000.00
			Logisti	ical					
Method			Fix	ed					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Community		Good	01/01/2020	01/01/2030	5:00	10:00	1	8,000.00	9,274.19
								8,000.00	9,274.19
Comments									



2024 - Sign replacement: street diagram- 6/2024 cost 1083.00



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

Storm Water	Drainaga	Donoire
Sioim water	THAINAGE :	- REDAILS

Item Number		55			Measu	rement Bas	Allow		
Туре	Type		Common Area		Estima	ited Useful I	_ife		5 Years
Category Tracking			Sev	Sewer		Cost			\$ 10,000.00
			Logisti	cal					
Method			Fix	red					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Community		Good	01/01/2025	01/01/2030	5:00	5:00	1	10,000.00	11,592.74
								10,000.00	11,592.74
Comments									



Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

# Component List - Full Detail

Wall	<b>Block</b>	- Re	nair
vvan	DIOCK	110	pun

Item Number		52 Common Area			2 Measurement Basis				LF
Туре					Estima	ited Useful I		5 Years	
Category		Walls, Gates, Fence			Basis Cost				\$ 45.00
Tracking			Logisti	cal					
Method			Fix	ed					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Community		Good	01/01/2020	01/01/2025	0:00	5:00	325	14,625.00	14,625.00
							_	14,625.00	14,625.00
Comments									

# .....





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

Item Number		53			Measu	urement Bas	Allow		
Туре	pe Common Area			rea	Estimated Useful Life				10 Years
Category		Windows, Doors			Basis (	Cost		\$ 2,500.00	
Tracking			cal						
Method			Fix	red					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse		Good	01/01/2020	01/01/2030	5:00	10:00	1	2,500.00	2,898.19
								2,500.00	2,898.19
Comments									





Analysis Date - January 1, 2025

Inflation:3.00% Investment:2.00% Contribution Factor:0.00% Calc:Future

Windscreen - Replace	ce
----------------------	----

Item Number		54			Measu	urement Bas	Allow		
Туре	pe Common Area			rea	Estimated Useful Life				10 Years
Category			Furniture			Cost			\$ 2,500.00
Tracking			cal						
Method			Fix	red					
			Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Condition	Date	Date	Life	Life	Quantity	Cost	Cost
Clubhouse		Good	01/01/2015	01/01/2025	0:00	10:00	1	2,500.00	2,500.00
								2,500.00	2,500.00
Comments									



